RTR Services Inc.							RTR #: 410349						6-15								
HEAVY TRUCK								ACCOUNT NUMBER:													
CONDITION REPORT			RT		را			3 (8) (8)			ACCOUNT NAM										
YEAR:		2023		MI	LES	207,94	0	VI	VIN #: 4		4V4NC9EH2PN622066										
MAKE:		Volvo		G۱	GVW: 5		50 LICENSE:					ST:		TAGS:	MONT	MONTH		YR:			
MODEL:		VNL 760		WI	WHEELBASE:		246"		COL	COLOR: EX		TERIOR: Blue			INTER	INTERIOR:		Grey			
ENGINE:		Volvo D13		HF	HP 455		BODY TYPE:		Sleeper		KEYS: IGNITION:		N: 🛛 YES	□NO	NO • DOOR: [YES	□ NO			
TRANS:		Automatic		FU	FUEL: GAS		⊠ DIESEL		NTIFR	NTIFREEZE		ESTED: YES NO		NO	RATII	ATING:					
DOES N		IOTOR RUN? XES		s	S NO		COLLISION DAN		GE?	GE? 🛛 YE		□ №	NO								
PHYSICAL APPEARANCE																					
			GD	FR	PR	N/A	COMMEN	TS							OPTIONS						
BODY	FRONT BUMPER HEAD LIGHTS HOOD TURN SIGNALS				\boxtimes		Missing d	ssing driver side corner, bumper is bent down a little													
													BR	BRAKES ⊠ AIR							
			H		$I \vdash I$									□ H							
	GRILLE		ō	\boxtimes											☐ ☑ PWR LOCKS						
	D FRONT FENDER																				
	D DOO															MIRRO	_				
	REAR BUMPER						Missing d	Missing driver side mudflap									ONDI		R		
				\boxtimes				<u> </u>								☐ AIR RIDE SEAT D/P					
	P FRONT FENDER		4																		
	P FRONT DOOR														$\dashv $						
	P SLEEPER				\boxtimes		Missing b	otto	m fiber	glass	cove	er				AM F	MRAD	OIO			
	TOP		X			0.0/.075/	0 % 275/80R22.5 SIZE:									TAPE/CD/CB?					
	D FRONT D REAR A1 (S/D?)															SLEEPER SIZE? 2_ELECTRICAL PIGTAIL					
တ	D REAR A2 (S/D?)			\boxtimes	lΞ		80 % 275/80R22 SIZE: 50 % 275/80R22 SIZE:														
TIRES	P FRONT				\boxtimes			10 % 275/80R22 SIZE:								FUEL TANKS					
-	P REAR A1 (S/D?) P REAR A2 (S/D?)			\boxtimes			80 % 275/80R22 SIZE: 40 % SIZE:									SINGLE GAL					
	SPARE				ΙH		40 % %								\exists \Box	 ☑ DUAL GAL <u>150/100</u> ☐ MUD FLAPS 					
GLASS	WINDSHIELD						Cracked a	and a	a small	chip					WH	EELS					
	D FRONT DOOR															⊠ AL □ ST	LUMIN	UM			
	REAR WINDOW P FRONT DOOR				\parallel											⊟BU					
	MIRRORS			\boxtimes												☐ SF	OKE				
~	DASH DOOR PANELS SEAT(S) CARPET] 🛚												EXHA		S/D? <u>S</u>	<u>}</u>		
<u> </u>							Driver side tilt is broken, seat rocks and is ripped					_ 80	SPENS AI								
INTER							Dilver 3id	C till	13 010	Keri, 30	sat it	ocks an	и із прр	cu			RING				
≥	HEADLINER			\boxtimes																	
	SLEEPER		GD	FR	⊠ PR	UKN	Refrigera		oor is I		and	falls of	it				DEM A				
١.	ENGINI							Engine		on				ᅱ峕		BOX					
<u>K</u>		MISSION		\boxtimes													TAG A	XLE			
Ĭ		CLUTCH													$\sqcup \Box$	WET	KIT iary Po		ln:4		
MECHANICAL	DIFFERENTIALS BRAKES														-	Auxii	iary Po	ower	Unit		
	FRONT END				16										╛┇						
-	REAR																				
THI		RY/ELECTR A MECHANIC	AL INS	PEC	L L TION /	IT IS A	VISUAL INS	PECT	TION O	NLY / I	DEF	& DPF F	FUNCTION	ONS NOT V	VERIFIE	D. BUY	YER				
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE																					
COMMENTS: Mileage Unverified. Missing communicatin from VADA ECU. VADA unavailable.																					
5/8/2025																					
		EMPLOYEE'S FULL	NAME (F	PLEASE	E PRINT)		DATE	:	_	_			MPLOYEE'S	SIGNATU	RE			_		

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.