RTR Services Inc. BOX TRUCK					-	Ð			ACCOUNT NUMBER: 4113773								
CONDITION REPORT				-6		-01		ACCOUNT NAME:									
	YEAR: 2012			-	ES	203,089	,			VIN #: 5PVNE8JV5D4S52647							
	MAKE: Hino			GV		25950	BOX HEI	-		-	BOX LENGTH 26.8			VIDTH			
		268		-		BASE:						hite	INTER	-	White, Wood		
ENGINE: J08E-VC/V		В	HP								1						
TRANS:AutomaticDOES MOTOR RUN?			_	1								RATIN	IG:	Unknown			
	DOES M	DIOR RUN?		YES	ES 🛛 NO COLLISION DAMAGE? 🖾 YES 🗌 NO PHYSICAL APPEARANCE												
			GD	FR											OPTIONS		
	FRONT BUMPER				$\boxtimes$			-	inor Scratches								
	HEADLIGHTS				$\boxtimes$				Driver And Passenger Side					BRAKES			
BODY	HOOD TURN SIGNALS																
	GRILLE			$\square$			م										
				$\boxtimes$			De PWR							INDOWS			
	D DOOR D BOX				$\boxtimes$		Step Is Misssing										
							Dented Liftgate Has Dents And Scratches						PWR MIRRORS AIR CONDITIONER				
	TAILLIGHTS		_	$\bowtie$			Lingale II	IS DC	Sits And Scratches								
			$\boxtimes$			~	. ~										
	P FRONT FENDER			$\square$			Cracked A	nd So	cratches					AM FM RADIO □ _ CD / CB?			
	P BOX			$\boxtimes$											R SIZE?		
TIRES				$\boxtimes$			% SI	ZE:					$\square$		LUCENT ROOF		
				$\bowtie$			% S	ZE:							DME LIGHT		
	D REAR A2 (S/D?) P FRONT					$\boxtimes$		ZE: ZE:						SIDE DO			
	P REAR A1 (S/D?)			$\boxtimes$				ZE: ZE:							s GLE GAL 90_		
	P REAR A2 (S/D?)					$\boxtimes$		ZE:						DUAL GAL			
GLASS	SPARE WINDSHIELD						% SI	ZE:						MUD FL EELS	APS		
	D FRONT DOOR			$\bowtie$													
							Scratches										
0	P FRONT DOOR MIRRORS			$\boxtimes$													
	DASH DOOR PANELS SEAT(S) FLOORING						Missing Pa	rts						EXHAUST S/D?			
INTERIOR				$\boxtimes$								SUS	SPENSION				
				$\boxtimes$										ING			
	HEADLINER				$\square$		Black Mar	ks									
	SLEEPER BOX				Image: Constraint of the second secon			And	Dents						M AXLE E BRAKE		
$\vdash$		GD	FR					ENTS:					TOOL B	OX			
	ENGINE						□ Rep			A Blown I	Engin	e		LIFT/TA	G AXLE		
AL	TRANS					$\boxtimes$								RAMP LIFTGA	TE		
MECHANICAL	DIFFERENTIALS					$\boxtimes$		ly Da	amage To	To Front					A SYSTEM		
						$\boxtimes$		·									
	FRONT END REAR END					$\boxtimes$			es Are Dead								
	BATTERY/ELECTR					$\boxtimes$	□ Bat	teries									
тш						$\boxtimes$											
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE																	
CO	MMENTS	S: Mileage Unv	erified.	Oil F	Pan Is	Missing I	Bolts And Ha	s A H	lole In It, T	ne #6 Rod V	las Th	nrown Leavi	ng Meta	I Shaving	Is In The Engine		

 EMPLOYEE'S FULL NAME (PLEASE PRINT)
 2/17/2025

 All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.
 EMPLOYEE'S SIGNATURE

RTR Services Inc. • 395 Market St. NE Salem OR 97301 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125