RTR Services Inc.					RTR #: 5021946-04														
TRAILER CONDITION REPORT										ACCOUNT NUMBER: ACCOUNT NAME:									
YEAR: 2008		<u> </u>		BODY	TYPE:	Hoppe	r	,	VIN #: 1W1MAFYA98A250170										
	MAKE:	Wilson																	
MODEL:		DAPH-508			C	OLOR:	EXT	ERIOR:	White	Vhite			IN.	TERIOR:					
LENGTH:		41'			WIDTH:				HEIGHT:						GVW:				
HITCH:		☐ GOOSE NECK		⊠ PI	NTLE	☐ 5 TH	WHEEL	HEEL PIN					1 2 5/16" B <i>A</i>	 BALL					
		☐ YE	s	T T		COLLISION DAMA		GE?	E? ☐ YES ☒ NO				KEYS	:	☐ YES	⊠ NO			
								PHYSICAL APPEARANCE											
GD			FR	PR	N/A	COM	COMMENTS							OPTIONS					
вору	FRONT PANEL HITCH D SIDE PANEL SIDE DOOR (S) REAR PANEL REAR DOOR (S) P SIDE PANEL REAR BUMPER TOP													\square	AIR RIDE SUSPENSION				
							Donto	Dented AIR BRAK							SPRING SUSPENSION				
							Dente								CAL BRAKES				
					\boxtimes		☐ HYD BRAKE							_					
														_	SLIDER AXLE				
							Warped						WH	EELS					
						\boxtimes										☐ SPO	KE		
INTERIOR	FLOOR D SIDE PANELS FRONT PANEL P SIDE PANEL CARGO RAILS][]												STEE			
						\boxtimes											☐ ALUMINUM ☐ LIFT/TAG AXLE ☐ SPARE TIRE RACK ☐ HUB METER ☐ REEFER HRS ☐ TOOL BOX		
						\boxtimes													
	D REAR A1 (S/D?) D REAR A2 (S/D?) D REAR A3 (S/D?) D REAR A3 (S/D?) P REAR A1 (S/D?) P REAR A2 (S/D?) P REAR A3 (S/D?)						% 20	% 20 SIZE: 11R22.5											
TIRES							%		11R22.5										
							% SIZE:									□ ROLL UP REAR DOOR □ BATTERY □ LIFTGATE			
							% 20 SIZE: 11R22.5 % SIZE: 11R22.5												
						\boxtimes	%	SIZE:								G RAMP			
	SPARE		GD	FR	│ □ │ PR	UKN	% SIZE: N/A COMMENTS:							☐ TRANSLUCENT ROOF☐ INTERIOR LIGHTING					
ECHANICAL	TAILLIGHTS SIGNAL LIGHTS CLEARANCE LGT SLIDER AXLES REFRIGERATION LANDING GEAR AIR HOSE/GLAD						IN/A	Missing							1 1		G RAMP		
																BULL HOOKS			
													☐ E-TRACK LINING						
									υ γ										
ME								,											
					\boxtimes	☐ Missing ☐ Missing all													
	S IS NO			PEC		IT IS A V		NSPECTION ONLY / FOR REEFER UNITS: EMISSION					MISSIONS	S NO	VERIFIED, BUYER				
RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE																			
COMMENTS: Weathered, most of it is rusted out. Spare tank has a hole in it. Linage is cracked.																			
		EMPLOYEE'S FUL	I NAME "	DI EVE	E DDINITY		5/	16/2025 DATE					EMP	LOYEE'S SIG	2NATI	DE			
							ort is deer		and accurate	to the he	est of my	knowledo		the date listed					