| | | Ī | |
|---|------------------|---------------|--|
| | ervices Inc. | | RTR #: 5023522-01 |
| GENERAL EQUIPMENT | | | ACCOUNT |
| CONDITI | ON REPORT | | ACCOUNT NAME: |
| YEAR: | | | |
| MAKE: | | ☐ YES ⊠ NO | EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY |
| MODEL: | | | |
| S/N: | | ☐ NON-OPERAT | |
| POWER: | Kubota Diesel | UNTESTABLE | |
| DESCRIPTION: Trailer mounted vertical light tower | | | |
| SHOT / COUNT / HOUR: Unknown. | | | |
| NOTES / COMMENTS: Hours Unverified. | | | |
| THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE | | | |
| | | | |
| RTR Se | ervices Inc. | | RTR #: |
| GENERAL | EQUIPMENT | | ACCOUNT |
| CONDITI | ON REPORT | | ACCOUNT NAME: |
| YEAR: | | | |
| MAKE: | | ☐ YES ☐ NO | EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY |
| MODEL: | | ☐ OPERATIONAL | |
| S/N: | | ☐ NON-OPERAT | IONAL |
| POWER: | | UNTESTABLE | |
| DESCRIPTION: | | | |
| SHOT / COUNT / HOUR: | | | |
| | | | |
| THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE | | | |
| | | | |
| | ervices Inc. | | RTR #: |
| | _ EQUIPMENT | | ACCOUNT |
| CONDITI | ON REPORT | | ACCOUNT NAME: |
| YEAR: | | | |
| MAKE: | | ☐ YES ☐ NO | EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY |
| MODEL: | | OPERATIONAL | |
| S/N: | | ☐ NON-OPERAT | |
| POWER: | | UNTESTABLE | |
| DESCRIPTION: | | | |
| SHOT / COUNT / HOUR: | | | |
| NOTES / COMMENTS: | | | |
| THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE | | | |
| 2/13/2025 | | | |
| EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE | | | |
| All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above. | | | |