	ervices Inc.		RTR #: 5093706
GENERAL EQUIPMENT			ACCOUNT
	ON REPORT		ACCOUNT NAME:
YEAR:	2010		
MAKE:	Vermeer	☐ YES ⊠ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:	24x40 II	<b>◯</b> OPERATIONAL	
S/N:	1VRZ19031A1000930	☐ NON-OPERATI	
POWER:	Diesel	UNTESTABLE	
DESCRIPTION: Navigator D24X40 Series II			
SHOT / COUNT / HOUR: Unknown (Unverified)			
NOTES / COMMENTS: Rust, Paint Chips, Missing Cap, Missing Screen. Container is strapped down.			
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE			
RTR Se	ervices Inc.		RTR #:
	<b>EQUIPMENT</b>		ACCOUNT
CONDITI	ON REPORT		ACCOUNT NAME:
YEAR:			
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:		☐ OPERATIONAL	L
S/N:		☐ NON-OPERATI	IONAL
POWER:		UNTESTABLE	
DESCRIPTION:			
SHOT / COUNT / HOUR:			
NOTES / COMMENTS:			
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE			
RTR Se	ervices Inc.		RTR#:
	EQUIPMENT		ACCOUNT
	ON REPORT		ACCOUNT NAME:
YEAR:			
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:		☐ OPERATIONAL	
S/N:		☐ NON-OPERATI	IONAL
POWER:		UNTESTABLE	
DESCRIPTION:			
SHOT / COUNT / HOUR:			
NOTES / COMMENTS:			
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE			
9/30/2025			
EMPLOYEE'S FULL NAME (PLEASE PRINT)  DATE  EMPLOYEE'S SIGNATURE			
All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.			