RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	3083158 # 5
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2018			
MAKE:	Biz Karts	☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	Eco Volt NG	☐ OPERATIONAL		
SN:	# 5	☒ NON OPERATIONAL		
POWER:	Electric	☐ UNTESTABLE		
DESCRIPTION:	Go Kart			
SHOT / COUNT / HOUR:				
NOTES / COMMENTS: Broke, disassembled, and does not run. Front end taken apart.				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	3083158 # 10
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2018			
MAKE:	Biz Karts	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	Eco Volt NG	☒ OPERATIONAL		
SN:	# 10	☐ NON OPERATIONAL		
POWER:	Electric	☐ UNTESTABLE		
DESCRIPTION:	Go Kart			
SHOT / COUNT / HOUR:				
NOTES / COMMENTS: Powered on. Battery fault as soon as turns on				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	3083158 # 4
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2018			
MAKE:	Biz Karts	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	Eco Volt NG	☒ OPERATIONAL		
SN:	# 4	☐ NON OPERATIONAL		
POWER:	Electric	☐ UNTESTABLE		
DESCRIPTION:	Go Kart			
SHOT / COUNT / HOUR:				
NOTES / COMMENTS: Powered on and runs.				

EMPLOYEE'S FULL NAME (PLEASE PRINT)	DATE	EMPLOYEE'S SIGNATURE
	08/17/2023	

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	3083158 # 13
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2018			
MAKE:	Biz Karts	☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	Eco Volt NG	☒ OPERATIONAL		
SN:	# 13	☐ NON OPERATIONAL		
POWER:	Electric	☐ UNTESTABLE		
DESCRIPTION:	Go Kart			
SHOT / COUNT / HOUR:				
NOTES / COMMENTS: Powers on runs and drives.				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	3083158 # 21
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2018			
MAKE:	Biz Karts	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	Eco Volt NG	☒ OPERATIONAL		
SN:	# 21	☐ NON OPERATIONAL		
POWER:	Electric	☐ UNTESTABLE		
DESCRIPTION:	Go Kart			
SHOT / COUNT / HOUR:				
NOTES / COMMENTS: Powers on runs and drives.				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	3083158 # 12
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2018			
MAKE:	Biz Karts	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	Eco Volt NG	☒ OPERATIONAL		
SN:	# 12	☐ NON OPERATIONAL		
POWER:	Electric	☐ UNTESTABLE		
DESCRIPTION:	Go Kart			
SHOT / COUNT / HOUR:				
NOTES / COMMENTS: Powered on and runs. Missing wheel, right side frame parts.				

EMPLOYEE'S FULL NAME (PLEASE PRINT)	DATE	EMPLOYEE'S SIGNATURE
	08/17/2023	

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	3083158 # 16
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2018			
MAKE:	Biz Karts	☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	Eco Volt NG	☒ OPERATIONAL		
SN:	# 16	☐ NON OPERATIONAL		
POWER:	Electric	☐ UNTESTABLE		
DESCRIPTION:	Go Kart			
SHOT / COUNT / HOUR:				
NOTES / COMMENTS: Powers on runs and drives.				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	3083158 # 15
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2018			
MAKE:	Biz Karts	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	Eco Volt NG	☒ OPERATIONAL		
SN:	# 15	☐ NON OPERATIONAL		
POWER:	Electric	☐ UNTESTABLE		
DESCRIPTION:	Go Kart			
SHOT / COUNT / HOUR:				
NOTES / COMMENTS: Powers on runs and drives.				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	3083158 # 3
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2018			
MAKE:	Biz Karts	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	Eco Volt NG	☒ OPERATIONAL		
SN:	# 3	☐ NON OPERATIONAL		
POWER:	Electric	☐ UNTESTABLE		
DESCRIPTION:	Go Kart			
SHOT / COUNT / HOUR:				
NOTES / COMMENTS: Powered on and runs.				

EMPLOYEE'S FULL NAME (PLEASE PRINT)	DATE	EMPLOYEE'S SIGNATURE
	08/17/2023	

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	3083158 # 20
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2018			
MAKE:	Biz Karts	☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	Eco Volt NG	☐ OPERATIONAL		
SN:	# 20	☒ NON OPERATIONAL		
POWER:	Electric	☐ UNTESTABLE		
DESCRIPTION:	Go Kart			
SHOT / COUNT / HOUR:				
NOTES / COMMENTS: Powers on runs and drives.				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	3083158 # 17
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2018			
MAKE:	Biz Karts	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	Eco Volt NG	☐ OPERATIONAL		
SN:	# 17	☒ NON OPERATIONAL		
POWER:	Electric	☐ UNTESTABLE		
DESCRIPTION:	Go Kart			
SHOT / COUNT / HOUR:				
NOTES / COMMENTS: Does not power on. Broke and dissambled.				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	3083158 # 19
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2018			
MAKE:	Biz Karts	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	Eco Volt NG	☒ OPERATIONAL		
SN:	# 19	☐ NON OPERATIONAL		
POWER:	Electric	☐ UNTESTABLE		
DESCRIPTION:	Go Kart			
SHOT / COUNT / HOUR:				
NOTES / COMMENTS: Powered on and runs.				

EMPLOYEE'S FULL NAME (PLEASE PRINT)	DATE	EMPLOYEE'S SIGNATURE
	08/17/2023	

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107