RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	4031694
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2017			
MAKE:	Spudnik	☒ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	560	☒ OPERATIONAL		
SN:	560-55-488	☐ NON OPERATIONAL		
POWER:	480 VOLT 3ph	☐ UNTESTABLE		
DESCRIPTION:	Farm equipment used to convey and sort produce.			
SHOT / COUNT / HOUR: N/A				
NOTES / COMMENTS:				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:				
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:		☐ OPERATIONAL		
SN:		☐ NON OPERATIONAL		
POWER:		☐ UNTESTABLE		
DESCRIPTION:				
SHOT / COUNT / HOUR:				
NOTES / COMMENTS:				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:				
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:		☐ OPERATIONAL		
SN:		☐ NON OPERATIONAL		
POWER:		☐ UNTESTABLE		
DESCRIPTION:				
SHOT / COUNT / HOUR:				
NOTES / COMMENTS:				

4/9/2024

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107