RTR Services Inc. TRAILER CONDITION REPORT										RTR #: 40236 ACCOUNT NUMBER: ACCOUNT NAME:						02368(	D					
<b>YEAR:</b> 2012				BODY	TYPE:	Dry Van			VIN#: 5V8VA532				008	38								
MAKE:		Vanguard	√anguard		LIC	ENSE:				STATE:			TAGS: MN:			YR:						
MODEL:		MaxCube			COLOR:		EXTERIOR:		Wh	Vhite			INT		TERIOR:		White/Wood/Steel					
LENGTH: 53'				١	VIDTH:	102"			HEIGHT: 13'6"						<b>GVW:</b> 68,000							
				INTLE	<b>∑</b> 5 <sup>™</sup>	_			7/8" BALL 🗌 2" BALL													
IS IT ROAD READY? 🛛 YES				S			COLLISION DAMA						O KEYS:			: 🗌 YES			NO NO			
_								HYSICAL	APF	PEARAN	CE											
	FRONT	PANEL	GD	FR	PR	N/A	COMN	COMMENTS										OPTIONS				
орү	HITCH	FANEL		$\boxtimes$											SPRING SUSPENSION							
		D SIDE PANEL SIDE DOOR (S) REAR PANEL REAR DOOR (S)		$\boxtimes$																		
													ELECTRICAL BRAKES HYD BRAKES									
8				$\boxtimes$													□ HYD BRAKES □ SLIDER AXLE					
	P SIDE PANEL		$\boxtimes$											WHEELS								
			$\boxtimes$																			
	TOP 🗌		$\boxtimes$			<u> </u>																
NTERIOR	D SIDE PANELS		$\boxtimes$																JM			
				$\boxtimes$														LIFT/T/				
Ë	P SIDE PANEL			$\square$		$\square$																
=			$\boxtimes$														REEFE					
TIRES	D FRONT				$\boxtimes$	% SIZE:																
		D REAR A1 (S/D?)		$\boxtimes$				% 45 SIZE: 295/75R/22.5									ROLL UP REAR DOOR					
		D REAR A3 (S/D?)				$\square$																
	P FRO	P FRONT				$\boxtimes$	%	SIZE:										BATTE	RY			
	P REAR A1 (S/D?) P REAR A2 (S/D?) P REAR A3 (S/D?) SPARE			$\boxtimes$		$\square$	% 45 SIZE: 295/75R/22.5 % 45 SIZE: 295/75R/22.5															
							% 45 SIZE: 295//5R/22.5															
						│																
	TAIL LIGHTS		GD	FR	PR		N/A	COMME	ENTS	5:												
AL	SIGNAL LIGHTS			$\boxtimes$																		
CHANICAL		CLEARANCE LGT		$\boxtimes$																		
HAI		R AXLES GERATION		$\boxtimes \Box \boxtimes$			$\square$															
ш		NG GEAR																				
Σ	AIR HOSE/GLAD			$\boxtimes$																		
COMMENTS: Inside passenger front axle tire is bald.																						

02/13/2024

EMPLOYEE'S FULL NAME (PLEASE PRINT)

DATE

EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

RTR Services Inc. • 395 Market St. NE Salem OR 97301 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107