RTR Services Inc.			RTR #: 4023791-01	
GENERAL EQUIPMENT		ACCOUNT		
CONDITION REPORT		ACCOUNT NAME:		
YEAR:	2012		ACCOUNT NAME.	
MAKE:	Vermeer	☐ YES ⊠ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	BC1000XL	☐ OPERATIONA	<u> </u>	
SN:	1VRY11192C101852	□ NON OPERATIONAL		
POWER:	Diesel	UNTESTABLE		
DESCRIPTION:	DESCRIPTION: Wood Chipper mounted on a trailer			
SHOT / COUNT / HOUR: 2,011 Hours				
NOTES / COMMENTS: S/N: 1VRY11192C1018520. Tires: 225/75R/15. Needs new tires.				
RTR Services Inc. RTR #: 4023791-02				
GENERAL EQUIPMENT		ACCOUNT		
CONDITION REPORT		ACCOUNT NAME:		
YEAR:	2018			
MAKE:	Vermeer	☐ YES ⊠ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	SC552	<b>☑</b> OPERATIONA	Ĺ	
SN:	1VR9138U2J1000266	☐ NON OPERATIONAL		
POWER:	Diesel	UNTESTABLE		
DESCRIPTION:	DESCRIPTION: Stump cutter			
SHOT / COUNT / I	HOUR: 1,236 Hours			
NOTES / COMMENTS: S/N: 1VR9138U2J1000266. Blade is off the unit, assembly laying beside it.				
RTR Services Inc.				
GENERAL EQUIPMENT			ACCOUNT	
	ON REPORT		ACCOUNT NAME:	
YEAR:				
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:		☐ OPERATIONA	L	
SN:		□ NON OPERATIONAL		
POWER:		UNTESTABLE		
DESCRIPTION:		•		
SHOT / COUNT / HOUR:				
NOTES / COMMENTS:				
03/11/2024				
EMPLOYEE'S FULL NAME (PLEASE PRINT)  DATE  EMPLOYEE'S SIGNATURE				
EMPLOTEE 3 FULL NAME (PLEASE PRINT)  By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.				