RTR Services Inc.							n				RTR #: 403236							4						
HEAVY TRUCK									_		ACCOUNT NUMBER:													
CONDITION REPORT					Đ				Ħ		ACCOUNT NAME:													
YEAR:		2018		MII	LES	485,887					VIN#: 3AKJGLDR5JSHZ7176													
MAKE:		Freightliner	GV	<b>GVW:</b> 52,			00 LICENSE:					ST:			TAGS	: N	MONT	Ή		YR:				
MODEL:		Cascadia	WH	IEELI	BASE:	ASE:			-	COLOR:	TERIOR: Blue				II	NTER	lOI	R:	Gray	II.				
ENGINE:		DD15 14.8L	HP	42	:5	ВС	DDY TYPE: Sle			per	KEYS:	KEYS: IGNITION: ⊠ YES □			s □	NO • DOOR: ⊠ YES □ NO								
TRANS:		Automatic	FU	EL: [	GAS	$\boxtimes$	DIESEL					ES 🖂	NO											
DOES N		OTOR RUN?	TOR RUN?   X YES		□ NC	)	CA	N IT BE	DRIVEN?		⊠ YE	⊠ YES		□ NO COLLISI		ISION D	ION DAMAC		$\top_{\mathfrak{l}}$	☐ YES		10		
							PHYSICAL																	
			GD	FR	PR	N/A	1	COMM	IENTS	<b>3</b>										OPT	IONS			
BODY	FRONT	BUMPER								n Bu	Bumper/Scratches/Cracked					$\boxtimes$	PWR STEERING							
		LIGHTS					-	Faded							BR/		AKES ⊠ AIR							
	HOOD	SIGNALS					-	Scratched/Pa			nt Chipping.Cracked						ŀ		AIR ] HYD					
	GRILL		H				-	Bunge	e Cor	d Hol	Holding Hood and Grill Together					$\boxtimes$		WR LOC						
	D FRONT FENDER			$\boxtimes$												$\boxtimes$								
	D DOO					-										☐ PWR SEATS ☑ PWR MIRRORS								
	D SLEE REAR I			H														WK MIK IR CONI		FR				
	TAIL LI			$  \; \exists \;$		-													IR RIDE					
	REAR PANEL			$\boxtimes$														$\boxtimes$				ENSION		
		P FRONT FENDER P FRONT DOOR					-													ONV. 5 <sup>T</sup>				
	PSLEE						-						SLIDING 5 <sup>TH</sup> WHEEL AM FM RADIO			CCL								
	TOP	10				-													APE / CI					
RES	D FRONT				$\boxtimes$		_				22.5 SIZ							$\boxtimes$		LEEPER				
	D REAR A1 (S/D?) D REAR A2 (S/D?)				$\boxtimes$		-	00/00 % 295/75R22.5 SIZE: 10/10 % 295/75R22.5 SIZE:											LECTRI LAD HA		GTAIL			
		P FRONT					-				22.5 SIZ							_	_	LAD HA TANKS	INDS			
₽	P REAR A1 (S/D?)				$\boxtimes$						22.5 SIZ									SINGL	E GAL			
	P REAR A2 (S/D?)						20/20 % 295/75R22.5 SIZE:											DUAL		20_				
GLASS	SPARE WINDSHIELD D FRONT DOOR				믐				%		SIZE:							I⊠ WHI		UD FLA	PS			
							-											*****		] ALUM	INUM			
		REAR WINDOW				$\boxtimes$		Window Insulation/Sealant Coming off								STEEL □ BUD □ SPOKE □ EXHAUST S/D? S								
5	P FRONT DOOR MIRRORS						-																	
	DASH			믐	$+$ $\vdash$															s				
RIOR	_	PANELS					-	Scuffs	3											ENSION		<u> </u>		
N N	SEAT(S) CARPET			$\boxtimes$			Ī	Stained/Worn												AIR				
NTEF							-											☐ SPRING ☐ PAD						
=	HEADL SLEEP				ᅵ뮤		-											$\boxtimes$		ANDEM	AXLE			
			GD	FR	PR	UKI	N	N/A	N/A COMMEN			NTS:								NGINE E				
MECHANICAL	ENGIN						Ī		Oil le	eak o	n motor									OOL BO				
		TRANSMISSION CLUTCH DIFFERENTIALS																		FT/TAG 'ET KIT	AXLE			
AN																			••					
끙	BRAKE	BRAKES		$\boxtimes$																				
ME	FRONT END																							
	REAR I	END RY/ELECTR	H																					
COMMENTS: Mileage unverified. Low fuel																								
																			—					
2/23/2024																								
		EMPLOYEE'S FULL	NAME (I	PLEASE	PRINT	<u>')</u>			DA			-			E	MPLOYEE	'S SIG	NATU	RE					
							l info	rmation co			nis report to	be tru	ue and accu	ırate t						nt.				