


<b>RTR Services Inc. BUS CONDITION REPORT</b>				<b>RTR #:</b> 1022670-01			
		<b>ACCOUNT NUMBER:</b>					
		<b>ACCOUNT NAME:</b>					
<b>YEAR:</b>	2018	<b>MILES</b>	144,710	<b>VIN#:</b>	3ALACXFC6JDHN8592		
<b>MAKE:</b>	Freightliner	<b>GVW:</b>	29500	<b>LICENSE:</b>			
<b>MODEL:</b>	GM 40	<b>WHEELBASE:</b>		<b>ST:</b>			
<b>ENGINE:</b>	Cummins	<b>HP</b>	300	<b>BODY TYPE:</b>	Passenger		
<b>TRANS:</b>	Automatic	<b>FUEL:</b>	<input type="checkbox"/> GAS <input checked="" type="checkbox"/> DIESEL	<b>KEYS: IGNITION:</b>	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
				<b>DOOR:</b>	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
<b>DOES MOTOR RUN?</b>		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<b>CAN IT BE DRIVEN?</b>	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
				<b>COLLISION DAMAGE?</b>	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		
<b>PHYSICAL APPEARANCE</b>							
<b>BODY</b>		<b>GD</b>	<b>FR</b>	<b>PR</b>	<b>N/A</b>	<b>COMMENTS</b>	<b>OPTIONS</b>
	FRONT BUMPER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> PWR STEERING
	HEAD LIGHTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<b>BRAKES</b>
	HOOD	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> AIR
	TURN SIGNALS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> HYD
	GRILL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> PWR LOCKS
	D FRONT FENDER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> PWR WINDOWS
	D DOOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> PWR SEATS
	D SLEEPER	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/> PWR MIRRORS
	REAR BUMPER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Scatched	<input checked="" type="checkbox"/> AIR CONDITIONER
<b>TIRES</b>	TAIL LIGHTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> AIR RIDE SEAT D/P
	REAR PANEL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> AIR RIDE SUSPENSION
	P FRONT FENDER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> CONV. 5 <sup>TH</sup> WHEEL
	P FRONT DOOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> SLIDING 5 <sup>TH</sup> WHEEL
	P SLEEPER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/> AM FM RADIO
	TOP	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> TAPE / CD / CB? CD_
							<input type="checkbox"/> SLEEPER SIZE? _____
						<input type="checkbox"/> ELECTRICAL PIGTAIL	
						<input type="checkbox"/> GLAD HANDS	
						<b>FUEL TANKS</b>	
<b>GLASS</b>	D FRONT	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	50 % 295/75/22.5 SIZE:	<input type="checkbox"/> SINGLE GAL _____
	D REAR A1 (S/D?)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	20 % 295/75/22.5 SIZE:	<input checked="" type="checkbox"/> DUAL GAL 50_
	D REAR A2 (S/D?)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	% SIZE:	<input type="checkbox"/> MUD FLAPS
	P FRONT	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	50 % 295/75/22.5 SIZE:	<b>WHEELS</b>
<b>INTERIOR</b>	P REAR A1 (S/D?)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	20 % 295/75/22.5 SIZE:	<input checked="" type="checkbox"/> ALUMINUM
	P REAR A2 (S/D?)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	% SIZE:	<input type="checkbox"/> STEEL
	SPARE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	% SIZE:	<input type="checkbox"/> BUD
	WINDSHIELD	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> SPOKE
<b>MECHANICAL</b>	D FRONT DOOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> EXHAUST S/D? S_
	REAR WINDOW	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<b>SUSPENSION</b>
	P FRONT DOOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> AIR
	MIRRORS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> SPRING
	DASH	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> PAD
<b>MECHANICAL</b>	DOOR PANELS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> TANDEM AXLE
	DRIVER SEAT(S)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> ENGINE BRAKE
	CARPET	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/> TOOL BOX
	HEADLINER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> LAVATORY
	PASSENGER SEATS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> REFRIGERATOR
		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> FIRST AID KIT
		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> FIRE EXTINGUISHER
		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> VIDEO SYSTEM
	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Batteries replaced 04/2021	<input checked="" type="checkbox"/> LEATHER SEATS	
						<input checked="" type="checkbox"/> PASSENGER 110 OUTLETS	
<b>COMMENTS:</b> Mileage unverified. Emergency Escape Hatch, Passenger Overhead Storage. Scratches and dents throughout the body. Driver side quarter panel has damage near back in front of tire.							

03/05/2021

\_\_\_\_\_  
EMPLOYEE'S FULL NAME (PLEASE PRINT)

\_\_\_\_\_  
DATE

\_\_\_\_\_  
EMPLOYEE'S SIGNATURE

**RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421**

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107