RTR Services Inc. BUS CONDITION REPORT		RTR #:	1051607-01
		ACCOUNT NUMBER:	
		ACCOUNT NAME:	

YEAR:	2008	MILES	479,351	VIN#:	WKKA34DH783000695						
MAKE:	Setra	GVW:	50530	LICENSE:		ST:		TAGS:	MONTH		YR:
MODEL:	S417	WHEELBASE:	30	COLOR: EXTERIOR:	White	INTERIOR:	Gray				
ENGINE:	Series 60	HP		BODY TYPE:	Passenger	KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO					
TRANS:	Automatic	FUEL: ☐ GAS ☒ DIESEL		ANTIFREEZE TESTED: ☐ YES ☒ NO		RATING:					
DOES MOTOR RUN?	☒ YES	☐ NO	CAN IT BE DRIVEN?	☒ YES	☐ NO	COLLISION DAMAGE?	☒ YES	☐ NO			

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS
BODY	FRONT BUMPER	☐	☒	☐	☐	
	HEAD LIGHTS	☐	☒	☐	☐	
	HOOD	☐	☒	☐	☐	
	TURN SIGNALS	☐	☒	☐	☐	
	GRILL	☐	☒	☐	☐	
	D FRONT FENDER	☐	☒	☐	☐	
	D DOOR	☐	☒	☐	☐	
	D SLEEPER	☐	☐	☐	☒	
	REAR BUMPER	☐	☒	☐	☐	Cracked, paint chipping
	TAIL LIGHTS	☐	☒	☐	☐	
	REAR PANEL	☐	☒	☐	☐	
	P FRONT FENDER	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	P SLEEPER	☐	☐	☐	☒	
	TOP	☐	☒	☐	☐	
TIRES	D FRONT	☐	☒	☐	☐	% 50 SIZE: 315/80R22.5
	D REAR A1 (S/D?)	☐	☒	☐	☐	% 50 SIZE: 315/80R22.5
	D REAR A2 (S/D?)	☐	☒	☐	☐	% 50 SIZE: 315/80R22.5
	P FRONT	☐	☒	☐	☐	% 50 SIZE: 315/80R22.5
	P REAR A1 (S/D?)	☐	☒	☐	☐	% 50 SIZE: 315/80R22.5
	P REAR A2 (S/D?)	☐	☒	☐	☐	% 50 SIZE: 315/80R22.5
	SPARE	☐	☐	☐	☒	% SIZE:
GLASS	WINDSHIELD	☐	☒	☐	☐	
	D FRONT DOOR	☐	☒	☐	☐	
	REAR WINDOW	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	MIRRORS	☐	☒	☐	☐	
INTERIOR	DASH	☐	☒	☐	☐	
	DOOR PANELS	☐	☒	☐	☐	
	DRIVER SEAT(S)	☐	☒	☐	☐	
	CARPET	☐	☒	☐	☐	
	HEADLINER	☐	☒	☐	☐	
	PASSENGER SEATS	☐	☒	☐	☐	

		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☒	☐	☐	☐	Check Engine and SOS light on
	TRANSMISSION	☐	☒	☐	☐	☐	
	CLUTCH	☐	☒	☐	☐	☐	
	DIFFERENTIALS	☐	☒	☐	☐	☐	
	BRAKES	☐	☒	☐	☐	☐	
	FRONT END	☐	☒	☐	☐	☐	
	REAR END	☐	☒	☐	☐	☐	
	BATTERY/ELECTR	☐	☒	☐	☐	☐	

OPTIONS

- ☒ PWR STEERING
- BRAKES
  - ☒ AIR
  - ☐ HYD
- ☐ PWR LOCKS
- ☒ PWR WINDOWS
- ☒ PWR SEATS
- ☐ PWR MIRRORS
- ☒ AIR CONDITIONER
- ☒ AIR RIDE SEAT D/P
- ☒ AIR RIDE SUSPENSION
- ☐ CONV. 5TH WHEEL
- ☐ SLIDING 5TH WHEEL
- ☒ AM FM RADIO
- ☒ TAPE / CD / CB? CD_
- ☐ SLEEPER SIZE? _____
- ☐ ELECTRICAL PIGTAIL
- ☐ GLAD HANDS
- FUEL TANKS
  - ☒ SINGLE GAL _____
  - ☐ DUAL GAL _____
- ☒ MUD FLAPS
- WHEELS
  - ☒ ALUMINUM
  - ☐ STEEL
  - ☐ BUD
  - ☐ SPOKE
- ☒ EXHAUST S/D? S_
- SUSPENSION
  - ☒ AIR
  - ☐ SPRING
  - ☐ PAD
- ☒ TANDEM AXLE
- ☐ ENGINE BRAKE
- ☐ TOOL BOX
- ☒ LAVATORY
- ☐ REFRIGERATOR
- ☒ FIRST AID KIT
- ☒ FIRE EXTINGUSIHER
- ☒ VIDEO SYSTEM
- ☒ Overhead Luggage
- ☐

COMMENTS: Mileage unverified. Scratches and paint chipping on luggage storage doors.

06/07/2021

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107