RTR Services Inc. TRAILER CONDITION REPORT										RTR #: 1071526-01 ACCOUNT NUMBER: ACCOUNT NAME:									
YEAR: 2020			BODY	TYPE:	Drop	Deck		VIN#: 1TTE532C4L3155612											
MAKE: Transcraft					ENSE:			S	TATE:	TAGS: MN:					YR:				
MODEL: 554 C				COLOR:		EXTERIOR: BI		Black T	arp	INTERIOR:		Combo							
LENGTH: 53'				WIDTH:		102"		HE	IGHT:				GVW : 80,000			00			
HITCH: GOOSE NECK		ECK	□ P	INTLE	⊠ 5 TH	WHEE	L PIN] 1 7/8" B	7/8" BALL 🗌 2" BALL 🔲 2 5/16" BA			ALL							
IS IT ROAD READY? ⊠ YES					□ №			LISION DA					KEYS	i :	□ Y	ES	□NO		
							F	PHYSICAL	APPEAR	ANCE									
		GD	FR	PR	N/A	COM	COMMENTS								OPTIONS AIR RIDE SUSPENSION				
FRONT PANEL HITCH D SIDE PANEL SIDE DOOR (S) REAR PANEL REAR DOOR (S) P SIDE PANEL REAR BUMPER TOP		PANEL OOR (S) PANEL DOOR (S) PANEL					Tarp has rip on bottom by legs Rip on velcro-passenger rear Repair patch near front bottom passanger side							☐ SPRING SUSPENS ☐ AIR BRAKES ☐ ELECTRICAL BRA ☐ HYD BRAKES					
INTERIOR	CEILING														☐ S ☑ A LIFT SPA REF	TEEL LUMII /TAG RE TII IGER/ FER H	NUM AXLE RE RACK ATION UNIT IRS		
TIRES	D REAR A1 (S/D?) D REAR A2 (S/D?) D REAR A3 (S/D?) P FRONT P REAR A1 (S/D?) P REAR A2 (S/D?) P REAR A2 (S/D?) P REAR A3 (S/D?)						% SIZE: □ LOADING RA % SIZE: □ BATTERY								PS REAR DOOR RAMP				
	<u> </u>		GD	FR	PR	UKN	N/A	COMMI	ENTS:					ÌП					
CLEAF SLIDE REFRI LANDI AIR HO		GHTS L LIGHTS ANCE LGT R AXLES GERATION NG GEAR DSE/GLAD R PIGTAIL																	
CO	COMMENTS: Both Tool Boxes have damage.																		
8/12/21 EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE																			