RTR Services Inc. FLAT BED/TOW TRUCK CONDITION REPORT												RTR #: 20233 ⁴ ACCOUNT NUMBER: ACCOUNT NAME:							16-01					
YEAR: 2005			MI	MILES Unknow						VIN#: 1GDE4C1265F518206														
MAKE:		GMC	GV	'W:	17,5	500	BE	D WIDTH	I	BED LENGTH				TOW CAPACITY										
М	ODEL:	4500	WH	IEELI	BASE	:			C	COLOR: EXTERIOR: Red				INTERIOR:			G	ray						
Eľ	IGINE:	6.6L Diesel						KE			EYS: IGNITION: 🛛 YES 🗌 NO 🔸 DOOR:				🛛 YES 🗌 NO									
Т	RANS:	Automatic		FU	EL: [] GA	s 🖂 I	DIESEL AN			NTIFREEZE TESTED: 🗌 YES 🖾 NO					RATING:								
DOES MOTOR RUN?				s [🛛 NC)	CAN	I IT BE DRIVEN?			VES				DAN	IAGE?) [] YES		🛛 NO				
PHYSICAL APPE										APPEARA	NC	Έ												
ВОДҮ	FRONT		GD	FR	PR	N	/A	COMM	IENTS									57	OPTIONS					
		FRONT BUMPER HEAD LIGHTS		\boxtimes			╡┝											AKES						
	HOOD			\boxtimes			_									1	🗌 🗌 AIR							
		SIGNALS		\boxtimes] [-									HYD				
	GRILL						╡┼	Broke	n drivesi	veside lower							ᅴ님		PWR LOCKS PWR WINDOWS					
	D PROI		\mathbb{X}			╡┝									$\exists \Box$		PWR WINDOWS PWR SEATS							
	D PANI		\boxtimes		-	i h																		
	REAR			\boxtimes			Bent												R CONI					
	TAIL LI					╡┝	Missi	ng belts,	bro	ken plast	ic						-	AIR RIDE SEAT D/P AIR RIDE SUSPENSION						
	P FRO			╎┝┥	_	╡┼													I FM R			/IN		
	-	NT DOOR		\boxtimes			i h															CB?		
	P PANE		\boxtimes		-																			
TIRES	TOP				-	<u>-</u> +	00.0/	005/305	- 40									WHEEL LIFT						
	D FRONT D REAR A1 (S/D?)			\boxtimes					80 % 225 / 70R 19.5 SIZE: 70 % 225 / 70R 19.5 SIZE:							□ TANDEM AXLE								
	D REAR A2 (S/D?)							%		IZE														
	P FRONT			\boxtimes		[] [80 % 225 / 70R										FU		ANKS	-			
		P REAR A1 (S/D?) P REAR A2 (S/D?)		\boxtimes					225 / 70F									4				GAL	-	
	SPARE						<u>%</u> SIZE: %SIZE:								DUAL GAL MUD FLAPS									
		HIELD						Cracked																
SS		FRONT DOOR		\boxtimes] [_	ALUM		М		
LA	REAR WINDOW P FRONT DOOR			\boxtimes]											_	_	STEEL	•			
G	MIRRO			\boxtimes			╡┝											-	_	BUD SPOKI	F			
	DASH				-	5	Part o	f the das	sh is	s missing	, w	ires ex	kposed	ł							/D?			
RIOR	DOOR		\boxtimes														SUSPENSION							
ERI	SEAT(S	· .						Mold & mildew throughout, ripped Mold & mildew						AIR ⊠ SPRING										
INTI	FLOOR HEADL							Mold & mildew							-		PAD	G						
-	BED							hrougho		t										(LE				
MECHANICAL		_	GD	FR	PR	_	KN	N/A	COMM	EN	rs:									NCH				
		ENGINE TRANSMISSION					3											\exists		IOOKS ET KIT	/Cl	1AIN	-	
	CLUTCH						3											ㅓ님		OM				
	DIFFERENTIALS																			ATBED)			
	BRAKES																	SELF LOADER						
	FRONT END REAR END																_ ⊠ AIR COMPRESSOR							
	BATTE					3											ㅓ님							
	MMENTS	5: Mileage unk				Pan	els no									nout be	ody (of truc	k. M	issing	the	inner		
cor	nectors	and nuts for th	he batte	eries.	Unat	ole to	jump	or rep	place bat	teri	es/ unkno	wn	n mech	nanical	Ι.									

02/24/2022

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107