

<b>RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT</b>		<b>RTR #:</b> 2023959-01	
		<b>ACCOUNT</b>	
		<b>ACCOUNT NAME:</b>	
<b>YEAR:</b>	2019		
<b>MAKE:</b>	Valentini	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
<b>MODEL:</b>	Attila L2300	<input type="checkbox"/> OPERATIONAL	
<b>SN:</b>	2598	<input type="checkbox"/> NON OPERATIONAL	
<b>POWER:</b>		<input checked="" type="checkbox"/> UNTESTABLE	
<b>DESCRIPTION:</b>	3 Pt Stone Crusher Complete w/ 1,000 RPM PTO Shaft & Hydraulic Toplink		
<b>SHOT / COUNT / HOUR:</b>			
<b>NOTES / COMMENTS:</b> Scratched, rust, and missing paint. Missing tooth.			

<b>RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT</b>		<b>RTR #:</b> 2023959-02	
		<b>ACCOUNT</b>	
		<b>ACCOUNT NAME:</b>	
<b>YEAR:</b>	2020		
<b>MAKE:</b>	Maschio	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
<b>MODEL:</b>	Dominator	<input type="checkbox"/> OPERATIONAL	
<b>SN:</b>	Unknown	<input type="checkbox"/> NON OPERATIONAL	
<b>POWER:</b>		<input checked="" type="checkbox"/> UNTESTABLE	
<b>DESCRIPTION:</b>	DM Rapido 3000 Plus 10' Power Harrow w/ Seeder Attachment & Cultipacker Roller		
<b>SHOT / COUNT / HOUR:</b>			
<b>NOTES / COMMENTS:</b> Scratched and paint missing.			

<b>RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT</b>		<b>RTR #:</b>	
		<b>ACCOUNT</b>	
		<b>ACCOUNT NAME:</b>	
<b>YEAR:</b>			
<b>MAKE:</b>		<input type="checkbox"/> YES <input type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
<b>MODEL:</b>		<input type="checkbox"/> OPERATIONAL	
<b>SN:</b>		<input type="checkbox"/> NON OPERATIONAL	
<b>POWER:</b>		<input type="checkbox"/> UNTESTABLE	
<b>DESCRIPTION:</b>			
<b>SHOT / COUNT / HOUR:</b>			
<b>NOTES / COMMENTS:</b>			

03/14/2022

_____ EMPLOYEE'S FULL NAME (PLEASE PRINT)	_____ DATE	_____ EMPLOYEE'S SIGNATURE
By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.		

**RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421**

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107