RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:	3083690 # 2
				ACCOUNT	
				ACCOUNT NAME:	
YEAR:	2018				
MAKE:	Biz Karts	☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:	Eco Volt NG	☐ OPERATIONAL			
SN:	# 2	☒ NON OPERATIONAL			
POWER:	Electric	☐ UNTESTABLE			
DESCRIPTION:	Go Kart				
SHOT / COUNT / HOUR:					
NOTES / COMMENTS: Broke, disassembled, and does not run. Has extra motor. Missing front wheels, missing battery covers.					

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:	3083690 # 9
				ACCOUNT	
				ACCOUNT NAME:	
YEAR:	2018				
MAKE:	Biz Karts	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:	Eco Volt NG	☒ OPERATIONAL			
SN:	# 9	☐ NON OPERATIONAL			
POWER:	Electric	☐ UNTESTABLE			
DESCRIPTION:	Go Kart				
SHOT / COUNT / HOUR:					
NOTES / COMMENTS: Powered on and ran.					

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:	3083690 # 11
				ACCOUNT	
				ACCOUNT NAME:	
YEAR:	2018				
MAKE:	Biz Karts	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:	Eco Volt NG	☐ OPERATIONAL			
SN:	# 11	☒ NON OPERATIONAL			
POWER:	Electric	☐ UNTESTABLE			
DESCRIPTION:	Go Kart				
SHOT / COUNT / HOUR:					
NOTES / COMMENTS: Powered on. Battery has a charge. Fault light comes on as soon as turned on					

EMPLOYEE'S FULL NAME (PLEASE PRINT)	DATE	EMPLOYEE'S SIGNATURE
	08/17/2023	

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:	3083690 # 6
				ACCOUNT	
				ACCOUNT NAME:	
YEAR:	2018				
MAKE:	Biz Karts	☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:	Eco Volt NG	☐ OPERATIONAL			
SN:	# 6	☒ NON OPERATIONAL			
POWER:	Electric	☐ UNTESTABLE			
DESCRIPTION:	Go Kart				
SHOT / COUNT / HOUR:					
NOTES / COMMENTS: Broke, disassembled, and does not run. Has extra motor. Missing front wheels, missing battery covers.					

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:	3083690 # 8
				ACCOUNT	
				ACCOUNT NAME:	
YEAR:	2018				
MAKE:	Biz Karts	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:	Eco Volt NG	☒ OPERATIONAL			
SN:	# 8	☐ NON OPERATIONAL			
POWER:	Electric	☐ UNTESTABLE			
DESCRIPTION:	Go Kart				
SHOT / COUNT / HOUR:					
NOTES / COMMENTS: Powered on and ran.					

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:	3083690 # 1
				ACCOUNT	
				ACCOUNT NAME:	
YEAR:	2018				
MAKE:	Biz Karts	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:	Eco Volt NG	☐ OPERATIONAL			
SN:	# 1	☒ NON OPERATIONAL			
POWER:	Electric	☐ UNTESTABLE			
DESCRIPTION:	Go Kart				
SHOT / COUNT / HOUR:					
NOTES / COMMENTS: Powered on. Battery has a charge. Units does not move.					

EMPLOYEE'S FULL NAME (PLEASE PRINT)	DATE	EMPLOYEE'S SIGNATURE
	08/17/2023	

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	3083690 # 7
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2018			
MAKE:	Biz Karts	☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	Eco Volt NG	☒ OPERATIONAL		
SN:	# 7	☐ NON OPERATIONAL		
POWER:	Electric	☐ UNTESTABLE		
DESCRIPTION:	Go Kart			
SHOT / COUNT / HOUR:				
NOTES / COMMENTS: Powered on and ran.				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	3083690 # 23
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2018			
MAKE:	Biz Karts	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	Eco Volt NG	☒ OPERATIONAL		
SN:	# 23	☐ NON OPERATIONAL		
POWER:	Electric	☐ UNTESTABLE		
DESCRIPTION:	Go Kart			
SHOT / COUNT / HOUR:				
NOTES / COMMENTS: Powered on and ran. Rear end rubs.				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	3083690 # 18
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2018			
MAKE:	Biz Karts	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	Eco Volt NG	☒ OPERATIONAL		
SN:	# 18	☐ NON OPERATIONAL		
POWER:	Electric	☐ UNTESTABLE		
DESCRIPTION:	Go Kart			
SHOT / COUNT / HOUR:				
NOTES / COMMENTS: Powered on and ran. Steering column bent a little, pulls to the right.				

EMPLOYEE'S FULL NAME (PLEASE PRINT)	DATE	EMPLOYEE'S SIGNATURE
	08/17/2023	

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	3083690 # 24
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2018			
MAKE:	Biz Karts	☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	Eco Volt NG	☐ OPERATIONAL		
SN:	# 24	☐ NON OPERATIONAL		
POWER:	Electric	☐ UNTESTABLE		
DESCRIPTION:	Go Kart			
SHOT / COUNT / HOUR:				
NOTES / COMMENTS: Powered on and ran.				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	3083690 # 14
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2018			
MAKE:	Biz Karts	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	Eco Volt NG	☒ OPERATIONAL		
SN:	# 14	☐ NON OPERATIONAL		
POWER:	Electric	☐ UNTESTABLE		
DESCRIPTION:	Go Kart			
SHOT / COUNT / HOUR:				
NOTES / COMMENTS: Powered on and ran.				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	3083690 #22
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2018			
MAKE:	Biz Karts	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	Eco Volt NG	☒ OPERATIONAL		
SN:	# 22	☐ NON OPERATIONAL		
POWER:	Electric	☐ UNTESTABLE		
DESCRIPTION:	Go Kart			
SHOT / COUNT / HOUR:				
NOTES / COMMENTS: Powered on and ran. Steering pulls right.				

EMPLOYEE'S FULL NAME (PLEASE PRINT)	DATE	EMPLOYEE'S SIGNATURE
	08/17/2023	

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107