	RTR Ser PICK-UF							RTR #: 3113132 ACCOUNT NUMBER:									
CONDITION REPORT			Т	Ċ			ACCOUNT N										
<b>YEAR:</b> 2007		2007		V	IN:		1GDJC	33667F5118	1874			MILES:	285	285,696			
MAKE:		GMC	GMC			E:			STATE			TAGS:	MN:	/N:			
MODEL: S		Sierra 3500	С	АВ ТҮ	PE:	Crew	со	LOR:	EX	TERIOR:	White		INTER	IOR:	Gray	/ Leather	
	ENGINE:	V-8 6.6 L		к	EYS:	GNITIO	N: 🖂 YES 🗌 NO 🔸 DOOR: 🖂 YES 🗌 NO										
TRANS: Au		Automatic		F	UEL:			ESEL 🗌 H	HYBRID ANTIFREEZE TESTED				D: 🛛 YES		RATI	RATING	
DOES MOTOR RUN? 🗌 YES 🛛 NO 🛛 C						AN IT BE DRIVEN?							IAGE?		s 🛛	NO	
								PHYSICAL APPEARANCE									
	FRONT BUMPER		GD	FR	PR	N/A	COMN	COMMENTS							OPTIONS PWR STEERING		
	HEAD LIGHTS			$\boxtimes$											PWR B		
	HOOD			$\boxtimes$											PWR LC		Ne
λ	TURN SIGNALS GRILL			$\boxtimes$											PWR W PWR SE		V5
	D FRONT FENDER				$\boxtimes$			on front pan						$\square$	LEATHE	ER SE	
	D DOOR D REAR FENDER				$\boxtimes$		Dent on front door d/s rear door missing door handle         PWR MIRROR           Dent on panel         X         CRUISE CONT										
ворү	CARGO BED				$\boxtimes$		Scratches, dents and hole in middle of bed.										
	REAR BUMPER TAIL LIGHTS				$\square$		Plastic panel on mid bumper detached 🛛 TINTED GLAS							-			
	TAIL CIGHTS			$\boxtimes$			scrato	hed, dents							CUSTO		
	TAIL PIPE			$\boxtimes$											SUN RC		
	P FRONT FENDER P DOOR			$\boxtimes$											AM FM TAPE D		)
	P REAR FENDER			$\square$											CD PLA	YER	
	TOP D FRONT						20.9/	235/35R16	CI7E.						CUSTO 4 X 4	M WHI	EELS
ES	DREAR				$\boxtimes$			235/35R16 235/35R16							TOW PA	CKAG	GE
TIRE	P FRONT				$\square$		30 %	235/35R16	SIZE:								
-	P REAR SPARE						30 %	235/35R16 %	SIZE:								
SS	WINDSHIELD			$\square$				<i>,</i> ,,									
	D FRONT DOOR D REAR PANEL			$\boxtimes$													
GLASS	P FRONT DOOR			$\square$													
<sup>o</sup>	P REAR PANEL																
DASH		NDOW		$\boxtimes$													
ERIOR	DOOR PA	NELS		$\bowtie$			as heavy wa										
L SEAT(S) 도 CARPET					$\boxtimes$		Driver's seat ripped, p/s front and back missing levers Plastic liner. Hole in d/s rear seat floorboard.										
INT	HEADLINER						1 1030		11 0/3 100	1 30		Jara.					
	ENGINE		GD	FR	PR		N/A	COMMENT Cranks bu		art							
AL						$\boxtimes$				.ai t							
MECHANICAL	CLUTCH	CLUTCH															
CHA	BRAKES FRONT END			$\square$													
ME	REAR END			$\boxtimes$													
BATTERY/ELECTR     Image     Image     Image     Image       COMMENTS:     Mileage     unverified.																	
	WIWIEIN   3:	wheaye unv	enned	•													

12/7/2023

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE
By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107