RTR Services Inc.										RTR #: 312335					l			
GENERAL									A	ACCOUNT NUMBER:								
EQUIPMENT										ACCO	UNT N	AME:						
CONDITION REPORT																		
YEAR: 2015				VIN/SN:		502136	\F15											
MAKE: Honey Bee				⊠ WHEEL		☐ TRAC	K [STATION	TATIONARY SKIDMOUNTED									
MODEL: AF23		AF236 Flex	3 Flex Head			R:	EXTERIOR: Yellow INTERIOR:											
ENGINE:							KEYS: IGNITION: ☐ YES ☐ NO ☒ N/A • DOOR: ☐											
TRANS:										PROPANE CNG								
HRS:					DOES IT RU				⊠ NO	UNK		CAN IT BE DRIVEN?			☐ YES ☑ NO ☐ UNK			
				LENGTH:				WIDTH:		HEIGHT:			WEIGHT:					
									AL APPEA	RANCE								
	FRONT	GD	FR	PR	N/A	COMI	MENT	S							OPTION	_		
	FRONT	HEAD LIGHTS														STEERI BRAKE		
	HOOD													H		OSED (-	
BODY	TURN SIGNALS					\boxtimes									TINTE	D GLA	SS	
	GRILL															ONDITI	ONER	
	L FRONT FENDER L DOOR				\parallel										HEAT	EK IDE SE	ΛТ	
	L REAR PANEL													H		_	SPENSION	
	SAFETY LIGHTS															M RADI		
	REAR			\boxtimes												DECK		
	TAIL LIGHTS FRAME													님		LAYER FLAPS		
	TURN SIGNALS			H	ΙH										2WD	FLAPS		
	R FRONT FENDER			Ø	ΤÖ										4WD			
	R FRONT DOOR					\boxtimes									PTO			
	R REAR PANEL			\boxtimes											BLAD		_	
	WORK LIGHTS				1											(ET SIZI ER		
	L FRONT						70 %	20.5/6	5 10 SIZE						ROLL			
SES.	L REAR														PACTO	R		
R FRONT							70 % 20.5/65 10 SIZE: 70 % 235/80R16 SIZE:							BOOM		_		
R REAR WINDSH		FLD	Н		╁╫		70 %	233/8	URIO SIZE	:						ICHER _ NPER		
ASS	L DOOR															K WIDT		
Ϋ́	REAR WINDOW					\boxtimes										RATOR	₹	
ਰ R DOOR																_TS		
	MIRRORS DASH/GAUGES				H											TTS PRSR C	EM.	
OR		OOR PANELS												H		SIZE G		
						\boxtimes								\square		1 couple	er-single_	
INTER		CARPET/MAT				\square									ROP			
	CONTRO	CONTROLS		FR	PR	UKN	N/A	COL	MMENTS:							TANKS JARY H		
	ENGINE		GD				N/A	501	THE INTO.						AUNIL	ייבועו ו	טטוו	
	TRANSMISSION					\boxtimes												
CLUTCH DIFFERI 2 ND DIFF UNDERG BRAKES							\boxtimes											
		CARRIAGE																
		_																
Σ	FRONT END			\boxtimes														
	REAR END BATTERY/ELECTR																	
CO			nnear	to b	e funct	ional 5		naint	chine thro	uahout th	e attachn	nent		ш				
	COMMENTS: The system appears to be functional. Rust and paint chips throughout the attachment.																	
							4 ^	E 00	24									
	EMI	PLOYEE'S FULL	NAME (D	FVCE	PRINT\		1-0	5-20	24 TE			EMDI	OYEE'S SIG	NAT	IRF			
	⊏IVI	TULL		ニニハンニ	· IMINI)			υA				LIVIEL	~ . ∟∟ J JIU		-: \ ⊏			