RTR Services Inc. BOX TRUCK					and a					ACCOUNT NUMBER:							
CONDITION REPORT			MILES 3.954					ACCOUNT NAME: VIN#: 54DB4W1DXMS203162									
MAKE: Isuzu			GVW:		3,954	BOX HEI			BOX LENGTH			BOX WIDTH					
MODEL: NPR			-	IEELB	ASE:				LOR: E	XTERIOR:			INTERIOR: Gray				
ENGINE: 8-Cyl 6.6L		HP	HP			ĸ	EYS:	EYS: IGNITION: 🛛 YES 🗌 NO 🔸 DOOR:			OOR: [
TRANS: Automatic			FU	FUEL: 🛛 GAS 🗌			L A	NTIF	NTIFREEZE TESTED: 🗌 YES 🖾 NO				RATING:				
DOES MOTOR RUN? X YES			s [С		E DRIVE					N DAM	AGE?		B 🛛 NO		
								PHYSIC	AL AP	PEARA	NCE						
BODY	FRONT BUMPER HEAD LIGHTS HOOD TURN SIGNALS		GD	FR	PR	N/A	COM	MENTS						OPTIONS			
	GRILL			\boxtimes											PWR LC	OCKS	
	D FRONT FENDER			\boxtimes												NDOWS	
	D DOOR D BOX														PWR SE PWR MI		
								AIR CC								NDITIONER	
	TAIL LIGHTS REAR PANEL			\boxtimes												E SEAT D/P E SUSPENSION	_
	P FRONT FENDER			\boxtimes										\boxtimes	AM FM I	RADIO	
	P FRONT DOOR P BOX			\square										_	-	CD / CB? R SIZE?	
	TOP			\boxtimes													
IRES	D FRONT			\boxtimes	70 % 215/85R												
	D REAR A1 (S/D?) D REAR A2 (S/D?)							70 % 215/85R/16 SIZE: % SIZE:						□ BOX DOME LIGHT □ SIDE DOOR FUEL TANKS □ SINGLE GAL □ DUAL GAL			
	P FRONT			\bowtie				70 % 215/85R/16 SIZE:									
-	P REAR A1 (S/D?) P REAR A2 (S/D?)						70 %	70 % 215/85R/16 SIZE: % SIZE:									
	SPARE							% SIZE:						MUD FLAPS			
LASS	WINDSHIELD D FRONT DOOR			\boxtimes									WHEELS				
	REAR WINDOW			\boxtimes								□ ALUMINUM ⊠ STEEL					
GL		P FRONT DOOR		\boxtimes												-	
	MIRRORS DASH			\boxtimes												KE ST S/D?	
~	DOOR PANELS			\boxtimes							SUSPENSION						
RIOR		SEAT(S)													🗆 AIR 🖾 SPRI	NG	
INTE																NO	
=	SLEEP	ER													TANDEM AXLE ENGINE BRAKE		
	BOX		GD	FR PR UKN N/A COM				COMM	IENTS:						TOOL B		
ECHANICAL	ENGINE			\boxtimes											LIFT/TA	G AXLE	
	TRANSMISSION CLUTCH			\square											RAMP LIFT GA	TE	
	DIFFERENTIALS			\boxtimes										\boxtimes	2022 Vic	tory CXI Sweepe	er
	BRAKES FRONT END			\boxtimes											Hours 1	06.9	
ME	REAR END			\boxtimes													
	BATTERY/ELECTR REFRIGERATION			\square													
COMMENTS: Mileage/Hours unverified. Sweeper unit has damage on passenger side vacuum sled and a bent hydraulic ram. The throttle on the																	
vacuum motor is not hooked up and is damaged. Swithches for the vacuum are damaged. The vacuum motor is hard to start and will only run a few minutes and shut down.																	
1000		and shut dow															
									24								
							02	2/20/202	24								

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107