RTR Services Inc. HEAVY TRUCK CONDITION REPORT		RTR #:	4023159
		ACCOUNT NUMBER:	
		ACCOUNT NAME:	

YEAR:	2002	MILES	883,768	VIN#:	1M2AG10C33M003743						
MAKE:	Mack	GVW:		LICENSE:		ST:		TAGS:	MONTH		YR:
MODEL:	Granite CV713	WHEELBASE:		COLOR: EXTERIOR:	Red	INTERIOR:	Tan				
ENGINE:	MACK AMI 12.0L	HP		BODY TYPE:	Roll Off	KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO					
TRANS:	18 Speed Manual	FUEL: ☐ GAS ☒ DIESEL		ANTIFREEZE TESTED: ☐ YES ☒ NO		RATING:					
DOES MOTOR RUN?	☒ YES	☐ NO	CAN IT BE DRIVEN?	☒ YES	☐ NO	COLLISION DAMAGE?	☐ YES	☒ NO			

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS
BODY	FRONT BUMPER	☐	☒	☐	☐	
	HEAD LIGHTS	☐	☒	☐	☐	
	HOOD	☐	☒	☐	☐	
	TURN SIGNALS	☐	☐	☒	☐	
	GRILL	☐	☒	☐	☐	
	D FRONT FENDER	☐	☒	☐	☐	
	D DOOR	☐	☒	☐	☐	
	D SLEEPER	☐	☐	☐	☒	
	REAR BUMPER	☐	☒	☐	☐	
	TAIL LIGHTS	☐	☐	☒	☐	Missing lights
	REAR PANEL	☐	☒	☐	☐	
	P FRONT FENDER	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	P SLEEPER	☐	☐	☐	☒	
	TOP	☐	☒	☐	☐	
TIRES	D FRONT	☐	☒	☐	☐	% SIZE:
	D REAR A1 (S/D?)	☐	☒	☐	☐	% SIZE:
	D REAR A2 (S/D?)	☐	☒	☐	☐	% SIZE:
	P FRONT	☐	☒	☐	☐	% SIZE:
	P REAR A1 (S/D?)	☐	☒	☐	☐	% SIZE:
	P REAR A2 (S/D?)	☐	☒	☐	☐	% SIZE:
	SPARE	☐	☐	☐	☒	% SIZE:
GLASS	WINDSHIELD	☐	☐	☒	☐	Passenger side scratched
	D FRONT DOOR	☐	☒	☐	☐	
	REAR WINDOW	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	MIRRORS	☐	☒	☐	☐	
INTERIOR	DASH	☐	☒	☐	☐	
	DOOR PANELS	☐	☒	☐	☐	
	SEAT(S)	☐	☒	☐	☐	
	CARPET	☐	☐	☐	☒	
	HEADLINER	☐	☒	☐	☐	
	SLEEPER	☐	☐	☐	☒	

		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☒	☐	☐	☐	Low on oil
	TRANSMISSION	☐	☒	☐	☐	☐	
	CLUTCH	☐	☒	☐	☐	☐	
	DIFFERENTIALS	☐	☒	☐	☐	☐	
	BRAKES	☐	☒	☐	☐	☐	
	FRONT END	☐	☒	☐	☐	☐	
	REAR END	☐	☒	☐	☐	☐	
	BATTERY/ELECTR	☐	☒	☐	☐	☐	Missing battery cover

OPTIONS
☒ PWR STEERING
BRAKES
☒ AIR
☐ HYD
☐ PWR LOCKS
☐ PWR WINDOWS
☐ PWR SEATS
☐ PWR MIRRORS
☒ AIR CONDITIONER
☒ AIR RIDE SEAT D/P
☒ AIR RIDE SUSPENSION
☐ CONV. 5TH WHEEL
☐ SLIDING 5TH WHEEL
☒ AM FM RADIO
☐ TAPE / CD / CB? _____
☐ SLEEPER SIZE? _____
☐ ELECTRICAL PIGTAIL
☐ GLAD HANDS
FUEL TANKS
☐ SINGLE GAL _____
☒ DUAL GAL _____
☒ MUD FLAPS
WHEELS
☒ ALUMINUM
☒ STEEL
☐ BUD
☐ SPOKE
☒ EXHAUST S/D? S_
SUSPENSION
☐ AIR
☒ SPRING
☒ PAD
☒ TANDEM AXLE
☒ ENGINE BRAKE
☒ TOOL BOX
☒ LIFT/TAG AXLE
☒ WET KIT
☒ TARP SYSTEM
☐
☐
☐
☐

COMMENTS: Mileage unverified. Fuel tank straps broken on passenger tank. Turn signals don't work.

03/14/2024

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107