RTR Services Inc.										RTR #: 404124						5					
HEAVY TRUCK							V-	-		ACCOUNT NUMBER:											
CONDITION REPORT			RT		فا						ACCOUNT NAME:										
YEAR:		2019			LES	595,80	)6				VIN#: 3A		AKJHHFG8KSLM8014		14						
MAKE:		Freightliner		G۷	<b>GVW:</b> 52,35			LICENSE:				5	ST:		TAGS:	MONT	Ή		YR:		
MODEL:		Cascadia		Wi	WHEELBASE:						OLOR: E	XTER	TERIOR: Red			INTERIOR: Gr			Gray		
ENGINE:		Cummins X15			,		BODY TYPE: SI			Slee	oer	KE	KEYS: IGNITION: ⊠ YES ☐			□ NO	] NO • DOOR: ⊠ YES □				
TRANS:		Automatic	FU	EL: [	GAS[	☑ DIESEL AN			ANT	FREEZE T	ESTE	ESTED:   YES   NO			RATIN	RATING:					
DOES N		OTOR RUN?	I? ⊠ YES		□ NO	) (	CANI	AN IT BE DRI		VEN? ⊠ YES		□ <b>!</b>	□ NO COLLISION DA		SION DA	MAGE?		☐ YES	⊠ N	10	
								PH	IYSIC/	AL AI	PPEARAN	CE									
ВОДУ			GD	FR	PR	N/A		OMMI											IONS		
	FRONT HEAD I	BUMPER		$\boxtimes$			So	cratch	ned, D	ent	nt										
	HOOD	101110					-							⊠ AIR							
	TURN SIGNALS			$\boxtimes$										$\exists$		] HYD					
	GRILL D FROM	NT FENDER			$\Box$													PWR LOCKS PWR WINDOWS			
	D DOO		$\boxtimes$	$\parallel$											$-\mid \boxtimes \mid$	<del>_</del>					
	D SLEEPER						Sc	Scratched										WR MIR			
	REAR BUMPER			$\boxtimes$			-											IR CONI IR RIDE			
	REAR	]	$\boxtimes$													A	IR RIDE	SUSPE	NSION		
		NT FENDER					So	Scratch, Removed Paint									☐ CONV. 5 <sup>TH</sup> WHEEL  SLIDING 5 <sup>TH</sup> WHEEL				
	P FROM					Sc	Scratch, Cracked										LIDING : M FM R/		EEL		
	TOP						Jordon Granda									T	APE / CI	) / CB?			
TIRES	D FROM						20 % 295/75R22.5 SIZE:														
	D REAR A1 (S/D?) D REAR A2 (S/D?)				$\boxtimes$			20 % 295/75R22.5 SIZE: 20 % 295/75R22.5 SIZE:								$\dashv                   $	- =				
	P FROM					20	20 % 295/75R22.5 SIZE:									FUEL TANKS					
	P REAR A1 (S/D?) P REAR A2 (S/D?)							20 % 295/75R22.5 SIZE: 20 % 295/75R22.5 SIZE:										] SINGL ] DUAL			
	SPARE								%		IZE:							UD FLA		<u>.u_</u>	
GLASS	WINDS	][											WH		-						
	D FRONT DOOR REAR WINDOW P FRONT DOOR															□ ALUMINUM □ STEEL					
GL				$\boxtimes$													BUD				
	MIRRO				$\vdash \vdash$	-										☐ SPOKE ☑ EXHAUST S/D? S_					
ď	DASH	PANFI S			Scratches													XHAUS I ENSION	S/D?	<u>&gt;</u>	
RIOR	DOOR PANELS SEAT(S)						Dı	Driver's Seat Torn							AIR						
NTE	CARPE	T	][															SPRIN	G		
<b>=</b>	HEADL SLEEP						м	issino	Matt	ress	es s					-	_	] PAD ANDEM	AXLE		
	<u> </u>		GD	FR	PR	UKN			COMI								ENGINE BRAKE				
MECHANICAL	ENGINI			$\boxtimes$											-			OOL BO			
		TRANSMISSION CLUTCH DIFFERENTIALS		$\boxtimes$												$\exists \exists$		ET KIT	AXLE		
							$\boxtimes$	]													
	BRAKES				ᅵᄆ																
		FRONT END REAR END			$\parallel$																
BATTE		RY/ELECTR			$\boxtimes$						d jumped										
COMMENTS: Mileage unverified. Missing Complete DPF Muffler System.																					
								414	. /0.5.5												
	<del></del>	EMBI OVESIO SIII		DI E	- pp		-	4/10	0/202						IDI OVEETE	0101:12:	DE			_	
		EMPLOYEE'S FULL By sig					informat	tion con	<b>DAT</b> tained w		is report to be	true and	d accurat		IPLOYEE'S of my know			nt.			