RTR Services Inc. EXCAVATOR WHEEL/TRACK CONDITION REPORT									RTR #: 406357 ACCOUNT NUMBER: ACCOUNT NAME:				' 6			
YEAR: 2013			VIN/S	N: 2	2065106											
MAKE: Komatsu						HEEL	- 🛛 TRACK									
MODEL: PC800LC-8					COLOR: E		R: Y	fellow INTERIOR: B			lack					
ENGINE: Komatsu SAA6D 5			A6D14	0E-								_				
TRANS: Hyd					FUEL: 🛛 DI		IESEL 🗌 GAS				🛛 NO	RA	TING:			
HRS: 15,140				DOES	IT RUN			NO UNK		CAN IT BE DRIVEN?		\square] UNK	
			GD	FR	PR	N/A	COMM		APPEARANCE					0	TIONS	
IOR GLASS TIRES BODY	FRONT PANEL HEAD LIGHTS HOOD TURN SIGNALS GRILL L FRONT PANEL L DOOR L REAR PANEL SAFETY LIGHTS REAR PANEL TAIL LIGHTS FRAME TURN SIGNALS R FRONT PANEL R FRONT DOOR R REAR PANEL WORK LIGHTS TOP L FRONT L REAR (S/D?) R FRONT R REAR (S/D?) R FRONT R REAR (S/D?) TRACKS WINDSHIELD L DOOR REAR WINDOW R DOOR MIRRORS DASH/GUAGES DOOR PANELS						Tracks Tracks Tracks Tracks Tracks 30% sc	% %	SIZE: SIZE: SIZE: SIZE: he rollers are f	frozen.				TINTED AIR CO HEATEI AIR RID AM FM TAPE D CD PLA BUCKE QUICK HYD TH	E SEAT RADIO ECK YER T COUPLEF	R
INTERI	SEAT CARPET/MAT CONTROLS			\boxtimes												
			GD	FR	PR		N/A	COMM	MENTS:							
ENGINE TRANSMISSION DIFFERENTIAL UNDERCARRIAGE BRAKES FRONT END REAR END BATTERY/ELECTR																
СО	COMMENTS: Hours unverified. Disassembled for transport.															

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107