RTR Services Inc.		RTR #: 4073446		
GENERAL EQUIPMENT			ACCOUNT	
CONDITION REPORT			ACCOUNT NAME:	
YEAR:	2020			
MAKE:	Vermeer	☐ YES ⊠ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	SC362	☐ OPERATIONA	L	
SN:	1VRF112YXM100408	NON OPERATIONAL		
POWER:	Vangaurd 35	UNTESTABLE		
DESCRIPTION:	Stump grinder			
SHOT / COUNT / HOUR: 642				
NOTES / COMMENTS: Hours unverified.				
DTD C			DTD #.	
	ervices Inc.		RTR #:	
	EQUIPMENT		ACCOUNT	
	ON REPORT		ACCOUNT NAME:	
YEAR:			T	
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:		OPERATIONAL		
SN:		□ NON OPERATIONAL		
POWER:		UNTESTABLE		
DESCRIPTION:				
SHOT / COUNT / HOUR:				
NOTES / COMMENTS:				
DED 0		.	DTD #	
	ervices Inc.	RTR #:		
GENERAL EQUIPMENT		ACCOUNT		
	ON REPORT		ACCOUNT NAME:	
YEAR:				
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:		☐ OPERATIONA	L	
SN:		☐ NON OPERAT	IONAL	
POWER:		UNTESTABLE		
DESCRIPTION:				
SHOT / COUNT / HOUR:				
NOTES / COMMENTS:				
7/04/0004				
7/31/2024				
EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.				
by signature above i do neieby certify an information contained within this report to be true and accurate to the best of this knowledge at present.				