RTR Services Inc. HEAVY TRUCK CONDITION REPORT										RTR #: 4103496-07 ACCOUNT NUMBER: ACCOUNT NAME:									
YEAR: 2023		MI	ES	231,136		VIN #: 4V4NC9EH5PN612874													
MAKE: Volvo		Volvo		GV	<b>GVW</b> : 50,		LICENSE:				ST: T		TAGS:	MON	тн	Y	R:		
MODEL: VNL 76		VNL 760		WH	WHEELBASE:				COLOR: EXTERIOR:		Yello	w	INTE	INTERIOR: Gray					
ENGINE: D13		D13							•										
TRANS: Automatic						DIESEL				RATI	RATING:								
DOES MOTOR RUN? VES ON COLLISION DAMAGE? VES NO PHYSICAL APPEARANCE																			
	GD			FR	PR	N/A									OPTIONS				
				$\boxtimes$										PWR STEERING					
	HEAD LIGHTS HOOD TURN SIGNALS			$\boxtimes$			-							BRAKES ⊠ AIR					
				$\boxtimes$															
	GRILLE													$ \square \boxtimes $	PWR I				
вору	D DOOR			$\boxtimes$											D PWR SEATS				
ă	D SLEEPER		$\boxtimes$	╞╋									$\square$	AIR C		-	ł		
			$\boxtimes$												-				
	REAR PANEL   P FRONT FENDER												$\exists$	AIR RI CONV		-			
	P FRONT DOOR		$\boxtimes$											SLIDING 5 <sup>TH</sup> WHEEL					
	P SLEEPER		$\boxtimes$																
	D FRONT			$\boxtimes$			70 % 295/7	-							☑     SLEEPER SIZE?       ☑     ELECTRICAL PIGTAIL				
ŝ	D REAR A2 (S/D?) $\Box$		$\boxtimes$			60/60 % 295/75 R22.5 SIZE: 60/60 % 295/75 R22.5 SIZE:													
TIRES	P FRONT		$\boxtimes$			70 % 295/75 R22.5 SIZE: 40/50 % 295/80 R22.5 SIZE:							FU	FUEL TANKS					
	P REAR A2 (S/D?)		$\boxtimes$			40/50 % 295/80 R22.5 SIZE: 40/40 % 295/80 R22.5 SIZE:								☐ SINGLE GAL					
	SPARE					% SIZE:								MUD FLAPS					
% D FRO ⊄ REAR		NT DOOR		$\boxtimes$												υΜΙΝ	м		
		NINDOW	$\boxtimes$										_						
0	MIRRORS			$\boxtimes$															
R	DASH DOOR PANELS																/D? <u>S</u>		
DOOR			$\boxtimes$									_ 50	SUSPENSION						
INTE	CARPE																		
≤	HEADLINER			$\boxtimes$										$\dashv$	☐ PA TAND		LE		
	ENGINE		GD	FR	PR	UKN		MME	NTS:								AKE		
MECHANICAL	TRANSMISSION			$\boxtimes$											TOOL LIFT/T		<b>KLE</b>		
	CLUTCH		$\square$											WET H APU	KIT				
CHA	DIFFERENTIALS		$\boxtimes$											AFU					
ΒE			$\boxtimes$																
	REAR END Image: Constraint of the second			$\boxtimes$															
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE																			
		: Mileage Unv								2.00									
							3/31/25			_									
EMPLOYEE'S FULL NAME (PLEASE PRINT)   DATE   EMPLOYEE'S SIGNATURE     All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.   All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.																			
_			All Informa	uon cor	nained	within this re	port is deemed to be	e true	and accurate	io the b	est of my kn	iowiedge a	as of the date lis	ied abov	<i>е</i> .				

RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125