RTR Services Inc.									RTR #: 410349						6-14					
HEAVY TRUCK								ACCOUNT NUMBER:												
CONDITION REPORT				را				ACCOUNT NAME:												
YEAR:		2023		MI	LES	233,07	3,079			VIN #: 4V4NC9		NC9EH4	9EH4PN622067							
MAKE:		Volvo		G۱	GVW:		B50 LICENSE:					ST:	ST: TAGS:		MONTH		Y	R:		
MODEL:		VNL64T760		WI	WHEELBASE		246		COLOR:		EXTE	XTERIOR: Blue			INTER	INTERIOR:		lack		
ENGINE:		Volvo D13 12.8L		HF	<b>HP</b> 455		BODY TYPE:		Sleeper		KEYS: IGNITION: 🖂		: XES	YES   NO •		DOOR: ⊠ YES ☐ NO		□ NO		
TRANS:		Automatic			IEL: [	GAS	⊠ DIESEL		ANTIFREEZE		TESTED: ☐ YES ⊠ NO			Ю	RATING:					
DOES M		OTOR RUN?   XES		S	□ NC	) (	COLLISION DA	AMA	GE?	⊠ YE	⊠ YES □ NO		'							
PHYSICAL APPEARANCE																				
			GD	FR	PR	N/A	COMMEN	TS								(	PTIO	NS		
BODY	FRONT BUMPER HEAD LIGHTS HOOD TURN SIGNALS						Missing									PWR S	STEER	ING		
								Passenger side broken Fiberglass broken						BRA	_ BRAKES □ ⊠ AIR					
														HYD						
	GRILLE															PWR I		3		
	D FRONT FENDER			$\boxtimes$												PWR \				
	D DOOR															☐ PWR SEATS				
	D SLEEPER  REAR BUMPER		<u> </u>		+											<ul><li>✓ PWR MIRRORS</li><li>✓ AIR CONDITIONER</li></ul>				
	TAILLIGHTS		Ħ		$\parallel$											AIR R				
	REAR PANEL			$\boxtimes$												AIR R	IDE SU	JSPE	NSION	
	P FRONT FENDER						Fiberglass	s bro	ken, r	nissing	vent	t			☐ CONV. 5 <sup>TH</sup> WHEEL  SLIDING 5 <sup>TH</sup> WHEEL					
	P FRONT DOOR P SLEEPER			$\boxtimes$												SLIDII AM FN			EL	
	TOP		H		$\parallel$	1 1									$\exists$	TAPE		-		
TIRES	D FRONT				$\boxtimes$		25 % 295/									SLEE	PER S	ZE?		
	D REAR A1 (S/D?)			$\boxtimes$				50 % 295/75R22.5 SIZE:												
	D REAR A2 (S/D?) P FRONT						25 % 295/75R22.5 SIZE:									☐ ☐ GLAD HANDS FUEL TANKS				
	P REAR A1 (S/D?)						25 % 295/75R22.5 SIZE: 15 % 295/75R22.5 SIZE:								0-	☐ SINGLE GAL				
	P REAR A2 (S/D?)				$\boxtimes$		25 % 295/75R22.5 SIZE:								☑ DUAL GAL 100 ea.					
	SPARE						25 % 295/	75R	22.5 S	SIZE:						MUD	FLAPS			
GLASS	WINDSHIELD D FRONT DOOR						Cracked								_ wh	EELS ⊠ AL	LIMINI	184		
	REAR WINDOW		H															) IVI		
	P FRONT DOOR			$\boxtimes$												BU				
	MIRRORS															☐ SP				
~	DASH DOOR PANELS SEAT(S)															EXHA		/D? <u>S</u>	<u>-</u>	
INTERIOF															_ 508	PENSI AIF				
	CARPET															□ SP				
Z	HEADLINER						Missing fr	ont	sun vi	sors						☐ PA	D			
	SLEEP	ER			DB.		N/A C	78454	ENTO							TAND				
MECHANICAL	ENGINE		GD	FR ⊠	PR	UKN	N/A CO	ואואו <i>ר</i>	ENTS:							ENGIN TOOL		ANE		
		MISSION	ă												ᅥᆸ	LIFT/I		KLE		
	CLUTCH						$\boxtimes$									WET I	<b>KIT</b>			
	DIFFERENTIALS														니 뭐					
	BRAKES FRONT END		片																	
	REAR END		ĭ												╛					
	BATTE	RY/ELECTR		$\boxtimes$																
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE																				
COMMENTS: Mileage Unverified. Passenger side front wheel missing lugnut cover.																				
		-			-				-											
							5/6/20												_	
		EMPLOYEE'S FULL	NAME (F	PLEASE	PRINT	)		DATE		_			El	MPLOYEE'S	SIGNATU	RE				

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.