RTR Services Inc.					~ ~ ~					RTR #:	410385	1				
LOADER				The second				ACCOUN	ACCOUNT NUMBER:							
WHEEL/TRACK										UNT NAME:						
CONDITION REPORT						HE(0)	)									
YEAR: 2012					VIN/S	VIN/SN: A		693								
MAKE: Bobcat						HEEL 🛛										
	MODEL:	T750	Г750			DR: E	KTERIOR: White INTERIOR: Bla					ack				
ENGINE:		Kubota V3800					ION: 🛛 YES 🗌 NO 🗌 N/A 🔸 DOOR: 🗌 YES 🗌 NO 🖾 N/A									
TRANS: Hyd					FUEL	: 🛛 DI	$ESEL \square GAS \qquad ANTIFREEZE TESTED : \boxtimes YES \square NO$					RA	TING:	5/10		
HRS: 3,510					DOES	IT RUN						$\boxtimes$	YES DI NO DI UNK			
									L APPEARANCE							
	FRONT		GD			N/A	COMMENTS Rusted/Chipped Paint					OPTIONS				
вору	HEAD LIGHTS						Ruste							RBRAKES		
	HOOD			$\boxtimes$								$\boxtimes$		LOSED CAB		
	TURN SIGNALS					$\square$								ED GLASS		
	GRILL L FRONT FENDER						Bucto	d/Chip	and			$\boxtimes$	AIR (		R	
	L DOOR					$\square$	Rusie	u/Cnip	Jeu							
	L REAR PANEL				$\bowtie$		Ruste	d/Chip	bed					RIDE SUSPE	NSION	
	SAFETY LIGHTS						_					$\boxtimes$		FM RADIO		
	REAR TAIL LIGHTS				$\square$		Scrap	ed up /	missing piece					E DECK PLAYER		
	FRAME			$\square$										FLAPS		
	TURN SIGNALS												2WD			
	R FRONT FENDER				$\boxtimes$		Rusted/Chipped						4WD			
	R FRONT DOOR				$\square$		Ducto	d/Chim	aad				PTO			
	R REAR PANEL WORK LIGHTS						Rusted/Chipped						BUCKET SIZE <u>7'</u>			
	TOP			$\boxtimes$										CK WIDTH <u>1.</u>		
6	L FRONT							%	SIZE:				ROP			
TIRES	L REAR R FRONT					$\boxtimes$	% SIZE: % SIZE:					$\square$	25%	Tracks		
F	R REAR			ΙH		$\boxtimes$		%	SIZE:							
SS	WINDSHIELD					$\boxtimes$		,.								
	L DOOR															
GLAS:	REAR WI	EAR WINDOW		$\boxtimes$												
0	MIRRORS				ΙH											
~	DASH/GU	DASH/GUAGES														
		NELS			$\boxtimes$											
ШШ	SEAT	MAT			$\boxtimes$		Torn/ rips									
I	CARPET/MAT CONTROLS															
			GD	FR	PR	UKN	N/A	COM	IMENTS:							
				٩N												
_		TRANSMISSION CLUTCH														
MECHANICAL		DIFFERENTIAL		$\square$			$\square$									
<b>N</b>		2 <sup>ND</sup> DIFFERENTIAL														
EH I				$\boxtimes$												
ME		BRAKES FRONT END		$\boxtimes$												
	REAR END			$\boxtimes$				-								
	BATTERY/ELECTR															
COMMENTS: Hours unverified. Dents / Scratches throughout entire unit.																
L																

10/21/2024

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107