RTR Services Inc. HEAVY TRUCK CONDITION REPORT											RTR #: 4113406-01 ACCOUNT NUMBER: ACCOUNT NAME:										
YEAR: 2019			мп	ES	541,316			VIN#: 1FUJGLDR6KLKD8323													
MAKE:		Freightliner		GV	-	52,000					S1	-		TAGS:	мо	οΝΤΙ	4		YR:		
MODEL:		Cascadia		-	IEELE	,				COLOR: EXTERIOR: White				-		IOR:		Red			
ENGINE:		Detroit Diesel DD15		HP																	
	RANS:	10 Speed Ma			-																
-		OTOR RUN?		_								$\overline{\times}$ NO COLLISION DA							10		
	0010 m					0,				APPEARANCE							20		10		
			GD	FR	PR	N/A	COMM	IENTS										OPTI			
BODY	-	BUMPER		$\boxtimes$			Dirty									PWR S	STEE	RING	ì		
	HEAD	LIGHTS		$\boxtimes$												SRA		z			
	TURN SIGNALS GRILL D FRONT FENDER			$\boxtimes$										HYD							
							Coutto	al							-		PWR I	LOCKS WINDOWS			
	D DOO		$\boxtimes$			Scuffe	a								_	PWR S			)		
	D SLEE		$\boxtimes$												Ξ	PWR I	MIRF	ORS			
	REAR E		$\boxtimes$											AIR CONDITIONER AIR RIDE SEAT D/P							
	REAR		$\boxtimes$																ENSION		
	-	NT FENDER		M			Scuffe	d									CONV	-			
	P FROM P SLEE		$\boxtimes$											-		SLIDIN AM FN			EEL		
	TOP		$\boxtimes$													TAPE			?		
TIRES	D FRONT			$\boxtimes$				70 % 295/75R22.5 SIZE: 70 % 295/75R22.5 SIZE:						□ SLEEPER SIZE? _ □ ELECTRICAL PIG							
	D REAR A1 (S/D?) D REAR A2 (S/D?)			$\boxtimes$				295/75R 295/75R									GLAD			GTAIL	
	P FRONT			$\boxtimes$			70 %	295/75R	22.5	SIZE:							L TANI	KS			
	P REAR A1 (S/D?) P REAR A2 (S/D?) SPARE			$\boxtimes$			70 % 295/75R22.5 SIZE: 70 % 295/75R22.5 SIZE:														
															$\bowtie$	⊠ DUAL GAL MUD FLAPS					
s	WINDSHIELD			$\boxtimes$											<b>١</b>	NHE	ELS				
GLASS	D FRONT DOOR REAR WINDOW			$\square$															NUM		
GL	P FRONT DOOR			$\boxtimes$																	
	MIRRO DASH		$\boxtimes$												_						
R	-	PANELS		$\boxtimes$												_	PENSI		3/0 ?		
ERIOR	SEAT(S)			$\boxtimes$														र			
INTE	CARPET HEADLINER						Mat flo	poring											3		
=	SLEEP			$\boxtimes$			No mattress									□ PAD □ TANDEM AXLE					
			GD	FR	PR	UKN	N/A	COMM	IENT	'S:						Ξ	ENGIN	NE B	RAKE		
MECHANICAL	ENGINE TRANSMISSION CLUTCH DIFFERENTIALS BRAKES				$\boxtimes$			Multin	le ai	r leaks						_	TOOL				
								Difficult to manuever							[	<ul> <li>LIFT/TAG AXLE</li> <li>WET KIT</li> </ul>					
							□ Air won			uild					[						
	FRONT		$\square$					ntb	una												
	REAR E																				
CO		RY/ELECTR S: Mileage unv	verified.					Batteri	ies r	eplaced	(2/3/2025	)									
12/3/24																					

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at presen

RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107