RTR Services Inc.											RTR #: 4123749-01											
BOX TRUCK											ACCOUNT NUMBER:											
CONDITION REPORT					MILES 80.319						ACCOUNT NAME:											
YEAR: 2021					_	80,31				VIN #:]	1F65F5KN3M0A14963		63								
	MAKE:	Ford		GV		19,50	00 E	BOX HEIG	_	6'6"			LENG					WIDT	I	90.5"		
	ODEL:	F-59				BASE:		ı		COLOR:				Wh				RIOR		Bla	.ck	
E	NGINE:	V8 7.3L		HP						S: IGNI							: X YE	S 🗌	NO			
	RANS:	Automatic			JEL: ☐ GAS ☐ DIESEL ANTIFREEZE TESTED: ☐ YES ☐ NO									RAT	ING:							
	DOES M	OTOR RUN?	⊠ Y	YES	□ 1	00	COLL	ISION DA			YE		⊠ NO									
	PHYSICAL APPEARANCE GD FR PR N/A COMMENTS OPTIONS																					
	FRONT	GD	FR	PR 🖂	N/A	_	mmENTS nor dama										OPTIONS PWR STEERING BRAKES					
	FRONT BUMPER HEADLIGHTS						IVII	nor dama	age													
	HOOD			\boxtimes															AIR			
	TURN S	SIGNALS =		\boxtimes													\dashv \vdash		HYD	OCKS		
		T NT FENDER			H	H											ᅴ님			/INDOW	IS	
ВОБУ	D D00			\boxtimes																EATS	_	
B	D BOX	BUMPER		\boxtimes	믐	+ $-$											$-\mid \square$			IRROR NDITIO	-	
	TAILLIGHTS REAR PANEL P FRONT FENDER			$\boxtimes \mid \Box \mid$														AIF	R RIE	DE SEA	T D/P _	
				\boxtimes	H												\dashv \exists			DE SUS RADIO	PENSIC	N
	P FRONT DOOR P BOX			\boxtimes													ᅴ님		/ CE	_	_	
				\boxtimes																ER SIZI		
	TOP D FRONT			\boxtimes	H		0/. /	10 SIZE :	225/	70P10	5						$-\hspace{-0.1cm}\mid \boxtimes$			CK LINI	IT ROOI NG	F
	D REAR A1 (S/D?)							10 SIZE:									$\dashv $			OME LI	_	
ပ္သ	D REAR A2 (S/D?)						%		ZE:	701171									DE D	OOR		
TIRES	P FRONT			\boxtimes				10 SIZE :									FU	JEL T				
		R A1 (S/D?)						10 SIZE:		70R19.:	5										\L	_
	SPARE	R A2 (S/D?)					%		ZE: ZE:								\dashv \sqcap			L GAL		
	WINDSHIELD D FRONT DOOR REAR WINDOW P FRONT DOOR MIRRORS			\boxtimes														HEEL	.S			
SSY													☐ ALUMINUM ☐ STEEL				l					
GLAS				\boxtimes										BUD								
								ssing P s							□ SPOKE							
	DASH	DANELO]	Da	maged/N	Missi	ng piece	es						_		_	IST S/D	?	_
OR	DOOR PANELS SEAT(S) FLOORING					To	Torn						SUSPENSION AIR									
INTERIOR				\boxtimes			10	111										_	SPR	ING		
	HEADLINER			\boxtimes														_	PAD		_	
	SLEEPER BOX																ᅴ님			M AXLI E BRAK		
				FR	PR	UKN		COM	MEN	ITS:								то	OL E	зох		
_	ENGINE TRANSMISSION CLUTCH DIFFERENTIALS BRAKES FRONT END REAR END BATTERY/ELECTR			\boxtimes															T/TA	AG AXL	.E	
CAL							\boxtimes										╛	LIF	TGA			
Ā																				RA SYS	TEM	
MECHANICAL				\boxtimes															elvii	ng		
ME				\boxtimes										╛								
								Batte	eries	replace	ed 3	3/25										
TH		GERATION TAMECHANIO	CAL INS	DEC1	LION /	IT IS A	USU <i>A</i>	L INSPE	CTIO	N ONI Y	' / D	FF & I	DPF FII	NCT	IONS	NOT	VFRIF	IED F	BLIYE	R RFS	PONSIF	BLF
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE																						
COMMENTS: Mileage Unverified.																						
			_		_	_		7/76/75									_			_		_
	-	EMPLOYEE'S FUL	L NAME (P	LEASE	PRINT)	_	<u>2/26/25</u> da	ATE.						EMPL	OYEE'S	SIGNAT	URE				

EMPLOYEE'S FULL NAME (PLEASE PRINT)

All information contained within this rep	oort is deemed to be true an	d accurate to the best of my	knowledge as of the date lis	ted above.