RTR Services Inc.										RTR #: 412387					6			
BOX TRUCK CONDITION REPORT				an P				ACCOUNT NUMBER: ACCOUNT NAME:										
		2018			ES	341,683			VIN#: 3HAMMMML2JL711409									
MAKE: Inte		International	ational		W:	26,000 BOX HE		X HEIGHT	BOX LENGTH 26'			В	BOX WIDTH					
MODEL:		DuraStar 4300		WH	WHEELBA		ASE:		COLOR:	OLOR: EXTERIOR: White		IN	INTERIOR:			iray		
ENGINE:		Cummins ISB 6.7L		HP				KE	EYS: IGNITION: ⊠ YES □ NO • DOOF			R: ⊠	⊠ YES □ NO					
TRANS:		Automatic				GAS 🛭	DIESE	L AN	NTIFREEZE TESTED: YES NO		R	RATING:						
DOES MOTOR RUN? X YES			S [□NO	C	AN IT B	E DRIVEN			COL	LISION	AMA	GE?	⊠ YE	S	□NO		
			CD	ED	DD	NI/A	COM		L APPEAR	ANCE						DTI	ONC	
	FRONT BUMPER		GD	FR	PR 🖂	N/A	Ruste	MENTS ed						\boxtimes	OPTIONS PWR STEERING			
	HEAD LIGHTS HOOD TURN SIGNALS GRILL			\boxtimes									_	RAKES ⊠ AIR □ HYD				
				\boxtimes														
				\boxtimes											PWR LOCKS			
_ ≽	D FRONT FENDER D DOOR						Drive	rs side fen			PWR WINDOWS PWR SEATS							
BODY	D BOX				$ \; \exists \;$									=	PWR SEATS PWR MIRRORS			
	REAR BUMPER													=	AIR CONDITIONER AIR RIDE SEAT D/P			
	TAIL LIGHTS REAR PANEL			\square			Dama	Damage to back door						_		_	EAT D/P JSPENSIO	N
	P FROI	P FRONT FENDER			\boxtimes		Scrat		340K 4001					\boxtimes	AM FM RADIO			
	P FRONT DOOR P BOX			\boxtimes											TAPE /			_
	TOP				\boxtimes		Paint	chipped							SLEEPER SIZE? TRANSLUCENT ROOF			=
IRES	D FRONT D REAR A1 (S/D?)			\boxtimes				40 % 265/75R22.5G SIZE:						E-TRAC				
		D REAR AT (5/D?) D REAR A2 (S/D?)					40 %	40 % 11R22.5 SIZE: % SIZE:							☐ BOX DOME LIGHT☐ SIDE DOOR			
	P FRONT			\boxtimes				40 % 265/75R22.5G SIZE:							FUEL TANKS			
-	P REAR A1 (S/D?) P REAR A2 (S/D?)						40 % 11R22.5, some rust SIZE: % SIZE:							☐ SINGLE GAL ☐ DUAL GAL				_
	SPARE					% SIZE:							MUD FLAPS					
တ	D EBO	WINDSHIELD D FRONT DOOR					Chip in windshield					ELS □ ALU	MINI	IM				
GLAS	REAR	REAR WINDOW		\boxtimes											STE		J.W.	
ច	P FRONT DOOR MIRRORS			\boxtimes												_		
	DASH				H									☐ SPOKE ☐ EXHAUST S/D?				_
용		DOOR PANELS		\boxtimes											PENSIC	N		_
	0-///	SEAT(S) FLOORING		\boxtimes	\parallel										☐ AIR ☐ SPR	ING		
INTERI	HEADL	HEADLINER					Torn)		
_	SLEEPER BOX													☐ TANDEM AXLE ☐ ENGINE BRAKE				
	ВОХ		GD	FR	PR				ENTS:						TOOL E			
MECHANICAL	ENGINE			\boxtimes					d issues w ight is on	th the Turi	bocharg	er, check			LIFT/T	G A	XLE	
		MISSION		\boxtimes				J.Igillo I	.g 10 011						RAMP			
		CLUTCH												\square	LIFT G	ATE		
분		DIFFERENTIALS BRAKES		\boxtimes										H				
Ä	FRONT END			$\boxtimes \mid \square \mid$														
	REAR END		=	= =														
REFRIGERATION COMMENTS: Mileage unverified.						\square												
COMMENTO. MINEAGE UTIVETHIEU.																		
							1/	13/2025										
	-	EMPLOYEE'S FUL						DATE		·	umate to "	EMPLOYE						
		By si	ynature abo	ove I do	nereby	centity all ir	normation of	ontained withii	n this report to b	e true and acc	urate to the	pest of my kr	nowledg	e at pre	sent.			