RTR Services Inc.						<u> </u>	Ti Ti			RTR #: 412399						2					
HEAVY TRUCK								ACCOUNT NUMBER:													
CONDITION REPORT				وا			ACCOUNT NAME:														
YEAR:		2014			MILES 7747		75			VIN#:		3AKNGBDV5ESFR8837		3837							
MAKE:		Frieghtliner		GV	GVW : 59K		LICENSE:					ST: TA		TAGS:	M	ONTH		,	YR:		
MODEL:		Cascadia		WH	WHEELBASE:		250		•	COLOR: I		EXTERIOR: Green		n	IN	INTERIOR:		(Gray		
ENGINE:		Detroit DD13 (12.8L)		HP	HP 450		BODY TYPE:		Day	Cab	KEYS: IGNITION:		N: 🛛 YES	XES □ NO			DOOR: YES □ NO				
TRANS:		10 Speed	FU	EL: [GAS	⊠ DIESE	L /	ANTIFREEZE		TESTED: ☐ YES ⊠		NO	R	RATING:							
DOES M		OTOR RUN?	UN? XES)	CAN IT BE DRIV		'EN? ⊠ YES		□ NO COLLI		ISION DA	SION DAMAC		⊠ YE	S	□ N	10		
PHYSICAL API									PPEARAN	ICI	=										
			GD	FR	PR	N/A	COM	MENTS													
	FRONT HEAD L	BUMPER		\boxtimes										⊠ F BRAK	WR ST	ΙEΕ	RING				
BODY	HOOD TURN SIGNALS GRILL D FRONT FENDER			\boxtimes												⊠ AIR					
				\boxtimes										☐ HYD☐ PWR LOCKS☐ PWR WINDOWS							
						+ $=$	Dam	amaged, crack in fiberglass.													
	D DOO		\boxtimes			Danis	bamagea, orack in insergraps.							☐ PWR SEATS							
	D SLEEPER															□ □ □ □ □ □ □					
	REAR BUMPER			$\boxtimes\boxtimes$																	
	REAR PANEL																				
			10	\boxtimes]]										_	ONV.				
																_	LIDING	-		EEL	
	TOP			\boxtimes												_	APE /				
TIRES	D FRONT]][1			50 % 315/80R22.5 SIZE: 25 % 11R22.5 SIZE:								☐ SLEEPER SIZE? ☐ ELECTRICAL PIGTAIL					
	D REAR A1 (S/D?) D REAR A2 (S/D?)							5 11R22.5 5 11R22.5								_	LECTI			AIL	
	P FRONT			\boxtimes			50 %	50 % 315/80R22.5 SIZE: FUEL TANKS								S					
														☐ SINGLE GAL ☑ DUAL GAL							
	SPARE					1 8			22.5 SIZE:												
S	WINDSHIELD D FRONT DOOR			\boxtimes												WHE					
SY REAR				\boxtimes	$\ \cdot\ $												☑ ALU ☑ STE		UM		
		NT DOOR		\boxtimes										BUD							
		MIRRORS															SPO		0/00		
~	DASH DOOR PANELS SEAT(S)			\boxtimes													XHAU ENSIO		S/D?_		
RIOR					\parallel												Zitolo ☑ AIR				
INTEF	CARPET																SPR				
=	HEADLINER SLEEPER] PAD		XIF		
ECHANICAL		GD	FR	PR	UKN	N/A	COMM	1EN	ITS:							NGINE	E BF	RAKE			
	ENGINE															_	OOL E				
	TRANSMISSION CLUTCH			\boxtimes												=	.IFT/TA VET KI		IXLE		
	DIFFERENTIALS			\boxtimes													arp Sy		m		
	BRAKES				$\mid \Box \mid$																
Σ	FRONT END REAR END			\boxtimes		$\parallel \parallel$															
	BATTE	RY/ELECTR			\boxtimes																
COMMENTS: Miliage Unverified. Lift Cylinder is leaking hydraulic fluid. The dump bed won't go all the way up.																					
	12/26/2024																				
		EMPLOYEE'S FULL By sig					information (DATE contained wit		his report to be	e tru	e and accura		EMPLOYEE'S est of my know							