RTR Services Inc. HEAVY TRUCK CONDITION REPORT										RTR #: 5013073-01 ACCOUNT NUMBER: ACCOUNT NAME:								
<b>YEAR:</b> 2016		MIL	ES	19,195			VIN #: 1XPTDP0X0GD332383											
MAKE: Peterbilt		Peterbilt		GV	<b>GVW:</b> 66,000		LICENSE:				ST:		TAGS:	MON	гн	YR:		
<b>MODEL:</b> 367			WHEEL		BASE:			COLOR:	COLOR: EXTERIOR: White		•	INTERIOR: Gray						
ENGINE: Paccar MX-13		3 12.9L	HP		В	ODY TYPE:	Cı	rane	KEYS: IGNITION: 🛛 YES									
TRANS: 18 Speed			-	FU	EL: 🗌	GAS 🛛 DIESEL		A	NTIFREEZE TESTED: 🗌 YES 🖾 NO				RATI	RATING:				
DOES MOTOR RUN? VES DO COLLISION DAMAGE? VES DO NO																		
									. APPEARA	NCE								
	FRONT BUMPER		GD	FR			COMMENT Passenger	-	e hood cracked						OPTIONS			
	HEAD LIGHTS			$\square$			. usesge						BRAKES					
	HOOD TURN SIGNALS			$\boxtimes$			<u>.</u>							_	⊠ AIR □ HYD			
	GRILLE			$\boxtimes$											PWR LOCKS			
×	D FRONT FENDER																	
ворү	D DOOR D SLEEPER														□ ☑ PWR SEATS □ ☑ PWR MIRRORS			
	REAR BUMPER														AIR CONDITIONER			
	TAILLIGHTS REAR PANEL			$\boxtimes$										$\square$		E SEAT		
	P FRONT FENDER														CONV.	5 <sup>™</sup> WHE	EL	
	P FRONT DOOR																	
	P SLEEPER TOP														AM FM RADIO			
	D FRONT			$\boxtimes$			60 % 425/65R22.5 SIZE:								SLEEPER SIZE?			
	D REAR A1 (S/D?) D REAR A2 (S/D?)			$\boxtimes$	🖂 🗌 📄 🗍 60 % 11R24.5 \$										<ul> <li>☑ ELECTRICAL PIGTAIL</li> <li>☑ GLAD HANDS</li> </ul>			
TIRES	P FRONT			$\square$	□         □         60 % 11R24.5 \$           □         □         60 % 425/65R22										FUEL TANKS			
F				$\square$	□ □ 60 % 11R24.5 SIZE: ⊠								LE GAL					
	P REAR A2 (S/D?) SPARE						60 % 11R2		<u>SIZE:</u> ZE:					$\neg$		L GAL _		
	WINDSHIELD			$\square$											IEELS			
		NT DOOR WINDOW		$\boxtimes$										_				
GLA																		
MIRRO		RS				<u> </u>	Driver side	doo	or mirror da	maged								
ĸ		PANELS		$\boxtimes$											SPENSIO	ST S/D?		
SEAT(		6)																
INTE														_				
=	HEADLINER SLEEPER																	
			GD	FR	PR	UKN		ММЕ	ENTS:						ENGINE	E BRAKE	i i	
MECHANICAL	ENGINE TRANSMISSION			$\boxtimes$										⊣님	TOOL B	BOX AG AXLE		
	CLUTCH			$\square$											WET KI			
HAI	DIFFERENTIALS			$\boxtimes$														
VEC	BRAKES FRONT END													$\dashv$				
<	REAR END																	
BATTERY/ELECTR       Image: September 2014       Image: September 2014 <td></td>																		
RE	SPONSIE	BLE TO VALID	ATE / W	/E RE	COM	IEND YO	OU INSPECT F	PRIC	OR TO PUR	CHASE								
	MMENTS n-Opera	6: Mileage Unv tional)	erified.	2015	rassi	F800RA	L/L214 Articu	llatir	ig Boom, N	lissing	⊨merę	gency St	op, Contr	oller Ba	attery Pac	K and H	arness	
		- /																
							4/2/25											
		EMPLOYEE'S FULL						ATE			<b>.</b> .		MPLOYEE'S					
			All informa	ation cor	ntained v	vithin this re	port is deemed to b	be true	e and accurate t	o the best	ot my kr	iowledge as	ot the date lis	sted above	э.			

RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125