RTR Services Inc. TRAILER					RTR #: 5013404-01 ACCOUNT NUMBER:												
CONDITION REPORT YEAR: 2016					BODY TYPE: Dry Van VIN #: 1JJV532D1GL929459												
					BODY	ITPE:	Dry Va	n		VIN #: 1JJV532D1GL929459			9459				
MODEL:		Wabash Dry Van			~	OLOR:	EXTERIOR: White INTERIOR:						Silver				
LENGTH: 53'		-			WIDTH:		102"		HEIGHT:			IIN			GVW: 68,000		
HITCH:							WHEEL PIN				2 5/16" B/	,					
				_								KEYS					
								HYSICAL					INE I O				
			GD	FR	PR	N/A	COMN	IENTS							OPT	IONS	
орү	-	PANEL		\boxtimes										\boxtimes	AIR RIDE	SUSPENSION	
		ΡΔΝΕΙ		\boxtimes										SPRING SUSPENSION AIR BRAKES			
	D SIDE PANEL SIDE DOOR (S) REAR PANEL					\square										CAL BRAKES	
BO				\boxtimes											HYD BRA	-	
				\boxtimes			Slight damage to lower panel								SLIDER AXLE		
	REAR BUMPER			\boxtimes		ongin	duniuge						1				
					<u> </u>												
NTERIOR	FLOOR				\boxtimes										STEEL		
	FRONT PANEL				\boxtimes										LIFT/TAG		
Ë	P SIDE PANEL			\boxtimes	\square									-	RE RACK		
_ ≤														HUB MET REEFER I			
TIRES	D REAR A1 (S/D?)					%		295/75R/2						TOOL BO	x		
	D REAR A2 (S/D?) D REAR A3 (S/D?)				\square		% %	SIZE:	295/75R/2	2.5					MUD FLA	PS REAR DOOR	
	P REAR A1 (S/D?) P REAR A2 (S/D?) P REAR A2 (S/D?) P REAR A3 (S/D?) SPARE			Н	\square	\square	%	-	295/75R/2	2.5					BATTERY		
					\bowtie		%		295/75R/2	22.5					LIFTGATE		
						\boxtimes	% %	SIZE: SIZE:								ICENT ROOF	
ECHANICAL	GD			FR	PR	UKN	N/A	COMMI	ENTS:							LIGHTING	
	TAILLIGHTS SIGNAL LIGHTS CLEARANCE LGT SLIDER AXLES REFRIGERATION LANDING GEAR AIR HOSE/GLAD			\boxtimes											LOADING BULL HO		
				\boxtimes											E-TRACK		
AAN I				\boxtimes										\boxtimes	SWING D		
				\square			\square								SIDE SKI	RTS	
Σ				\boxtimes													
	ELECTR PIGTAIL			\boxtimes				NODEOT				TO -	MICOLON				
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / FOR REEFER UNITS: EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE																	
COMMENTS: 2 blown out tires. Unit has no brakes. Mud flaps are bent.																	

2/19/25

EMPLOYEE'S SIGNATURE

EMPLOYEE'S FULL NAME (PLEASE PRINT)

DATE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above

RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125