RTR Services Inc.									RTR #: 5013875		
BOX TRUCK					ans		: :: : : :		ACCOUNT NUMBER:		
	CONDI	TION REPO	RT					А	CCOUNT NAME:		
	YEAR:	2018		MII	LES	420,558		VIN #:	5PVNE8JT8J4S575		
MAKE:		Hino		GV	W:	25,950 BOX HEI		GHT 7.5'	BOX LENGTH 24	l' BC	DX WIDTH 8'
MODEL:		268		WH	WHEELBASE:		21'	COLOR:	EXTERIOR: White	IN [.]	TERIOR: Black
EI	NGINE:	J08E 7.6L	J08E 7.6L					KEYS: IGNITI	ON: X YES INO •	DOOR: 🛛	YES NO
TRANS: Automatic			FUEL: ☐ GAS ⊠ DIESEL		ANTIFREEZE	TESTED: 🗌 YES 🖾 N	O RA	ATING:			
DOES MOTOR RUN?					 	10 C	OLLISION D	AMAGE? Y	ES NO	•	
							PHYS	SICAL APPEARA	NCE		
			GD	FR	PR	N/A	COMMENT	S			OPTIONS
	FRONT BUMPER HEADLIGHTS			\boxtimes							
	HOOD	IGHIS									☐ AIR
	TURN SIGNALS GRILLE			\boxtimes							⊠ HYD
											PWR LOCKS
	D FRONT FENDER D DOOR D BOX			$\boxtimes \boxtimes$							✓ PWR WINDOWS✓ PWR SEATS
ВОБУ							Bulged Or	ıt. Rivots Poppe	ed Out. Holes		□ PWR MIRRORS
æ	REAR BUMPER					\boxtimes	Duigua or	таков горр			
	TAILLIGHTS			\boxtimes							$oxed{oxed}$ AIR RIDE SEAT D/P ${ m D}$
	REAR PANEL				\boxtimes		Door On E	Blocks, Doesn't	Move		AIR RIDE SUSPENSION
	P FRONT FENDER			\boxtimes							M AM FM RADIO
	P FRONT DOOR P BOX						D4 II-1-				☐ CD / CB? CD ☐ SLEEPER SIZE?
	TOP						Dent, Hole	:			☐ TRANSLUCENT ROOF
TIRES	D FRONT			ă			% 0 SIZE:	11R22.5			E-TRACK LINING
	D REAR A1 (S/D?)			\boxtimes			% 50 SIZE	: 11R22.5			☐ BOX DOME LIGHT
	D REAR A2 (S/D?)				\boxtimes		% 10 SIZE	: 11R22.5			☐ SIDE DOOR
	P FRONT						% 5 SIZE :	11R22.5			FUEL TANKS
	P REAR A1 (S/D?)				\boxtimes		% 10 SIZE	: 11R22.5			SINGLE GAL
	P REAR A2 (S/D?)						% 10 SIZE				DUAL GAL
	SPARE WINDSHIELD						% S Chip And	IZE:			
SS	D FRONT DOOR REAR WINDOW P FRONT DOOR						Chip And	Cracked			ALUMINUM
GLAS				\square							STEEL
ত											BUD
	MIRRORS DASH			\boxtimes							☐ SPOKE ☐ EXHAUST S/D? S_
	DOOR PANELS										SUSPENSION
퐀	SEAT(S)						Driver Sid	e Is Ripped			□ AIR
SE	FLOORING			\boxtimes				• •			SPRING
INTERIOR	HEADLINER SLEEPER BOX										☐ PAD ☐ TANDEM AXLE
=							Unable To	Open Door, C	nipped And Broken		☐ ENGINE BRAKE
									Missing, Holes	., .,	
			GD	FR	PR	UKN		MMENTS:	<u>U</u>		TOOL BOX
MECHANICAL	ENGINI							eck Engine Lig	nt		☐ LIFT/TAG AXLE
	TRANSMISSION CLUTCH DIFFERENTIALS BRAKES FRONT END REAR END										□ RAMP⊠ LIFTGATE
											☐ CAMERA SYSTEM
				\boxtimes							
				\boxtimes	lΗ						
	BATTE	RY/ELECTR		\boxtimes							
TU		SERATION		DEC		IT IS A V	SIIAI INSDI	ECTION ON V (DEE & DDE EUNOTION	IS NOT VED	BUYER RESPONSIBLE
TO	VALIDA ⁻	TE / WE RECO	MMEN	D YOL	J INSF	ECT PRI	OR TO PURC	CHASE	LE & DEF FUNCTION	VER	II ILU, BU I EK KESPUNSIDLE
								a lot of damage			

	2/6/2025						
EMPLOYEE'S FULL NAME (PLEASE PRINT)	DATE	EMPLOYEE'S SIGNATURE					
All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above							