


| | | | | | | | |
|---|--------------------------|--|---|---|--|---|---|
| RTR Services Inc. BOX TRUCK CONDITION REPORT | |  | | RTR #: 5013875 | | | |
| | | ACCOUNT NUMBER: | | | | | |
| | | ACCOUNT NAME: | | | | | |
| YEAR: | 2018 | MILES | 420,558 | VIN #: | 5PVNE8JT8J4S57576 | | |
| MAKE: | Hino | GVW: | 25,950 | BOX HEIGHT | 7.5' | | |
| | | BOX LENGTH | 24' | BOX WIDTH | 8' | | |
| MODEL: | 268 | WHEELBASE: | 21' | COLOR: EXTERIOR: | White | | |
| | | INTERIOR: | Black | | | | |
| ENGINE: | J08E 7.6L | HP | | KEYS: IGNITION: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO • DOOR: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | | | |
| TRANS: | Automatic | FUEL: | <input type="checkbox"/> GAS <input checked="" type="checkbox"/> DIESEL | ANTIFREEZE TESTED: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | | | |
| DOES MOTOR RUN? | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | COLLISION DAMAGE? | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | | |
| PHYSICAL APPEARANCE | | | | | | | |
| BODY | | GD | FR | PR | N/A | COMMENTS | OPTIONS |
| | FRONT BUMPER | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input checked="" type="checkbox"/> PWR STEERING |
| | HEADLIGHTS | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | BRAKES |
| | HOOD | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input type="checkbox"/> AIR |
| | TURN SIGNALS | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input checked="" type="checkbox"/> HYD |
| | GRILLE | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input type="checkbox"/> PWR LOCKS |
| | D FRONT FENDER | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input checked="" type="checkbox"/> PWR WINDOWS |
| | D DOOR | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input type="checkbox"/> PWR SEATS |
| | D BOX | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Bulged Out. Rivots Popped Out, Holes | <input type="checkbox"/> PWR MIRRORS |
| | REAR BUMPER | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | | <input checked="" type="checkbox"/> AIR CONDITIONER |
| TAILLIGHTS | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input checked="" type="checkbox"/> AIR RIDE SEAT D/P D | |
| REAR PANEL | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Door On Blocks, Doesn't Move | <input type="checkbox"/> AIR RIDE SUSPENSION | |
| P FRONT FENDER | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input checked="" type="checkbox"/> AM FM RADIO | |
| P FRONT DOOR | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input checked="" type="checkbox"/> CD / CB? CD | |
| P BOX | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Dent, Hole | <input type="checkbox"/> SLEEPER SIZE? _____ | |
| TOP | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | | <input type="checkbox"/> TRANSLUCENT ROOF | |
| TIRES | D FRONT | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | % 0 SIZE: 11R22.5 | <input type="checkbox"/> E-TRACK LINING |
| | D REAR A1 (S/D?) | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | % 50 SIZE: 11R22.5 | <input type="checkbox"/> BOX DOME LIGHT |
| | D REAR A2 (S/D?) | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | % 10 SIZE: 11R22.5 | <input type="checkbox"/> SIDE DOOR |
| | P FRONT | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | % 5 SIZE: 11R22.5 | FUEL TANKS |
| | P REAR A1 (S/D?) | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | % 10 SIZE: 11R22.5 | <input type="checkbox"/> SINGLE GAL _____ |
| | P REAR A2 (S/D?) | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | % 10 SIZE: 11R22.5 | <input type="checkbox"/> DUAL GAL _____ |
| | SPARE | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | % SIZE: | <input checked="" type="checkbox"/> MUD FLAPS |
| GLASS | WINDSHIELD | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Chip And Cracked | WHEELS |
| | D FRONT DOOR | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input type="checkbox"/> ALUMINUM |
| | REAR WINDOW | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input type="checkbox"/> STEEL |
| | P FRONT DOOR | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input type="checkbox"/> BUD |
| INTERIOR | MIRRORS | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input type="checkbox"/> SPOKE |
| | DASH | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input checked="" type="checkbox"/> EXHAUST S/D? S_ |
| | DOOR PANELS | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | SUSPENSION |
| | SEAT(S) | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Driver Side Is Ripped | <input type="checkbox"/> AIR |
| | FLOORING | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input checked="" type="checkbox"/> SPRING |
| | HEADLINER | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | <input type="checkbox"/> PAD |
| SLEEPER | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | | <input type="checkbox"/> TANDEM AXLE | |
| BOX | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Unable To Open Door, Chipped And Broken Wood, Sections Of Plywood Are Missing, Holes | <input type="checkbox"/> ENGINE BRAKE | |
| MECHANICAL | | GD | FR | PR | UKN | N/A | COMMENTS: |
| | ENGINE | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Check Engine Light |
| | TRANSMISSION | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| | CLUTCH | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | |
| | DIFFERENTIALS | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| | BRAKES | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| | FRONT END | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| | REAR END | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| | BATTERY/ELECTR | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| REFRIGERATION | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | | |
| THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE COMMENTS: Mileage Unverified. Interior and exterior of box has a lot of damage | | | | | | | |

RTR Services Inc. • 395 Market St. NE Salem OR 97301 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125