


RTR Services Inc. BOX TRUCK CONDITION REPORT				RTR #: 5013875			
		ACCOUNT NUMBER:					
		ACCOUNT NAME:					
YEAR:	2018	MILES	420,558	VIN #:	5PVNE8JT8J4S57576		
MAKE:	Hino	GVW:	25,950	BOX HEIGHT	7.5'		
				BOX LENGTH	26'		
MODEL:	268	WHEELBASE:	21'	COLOR: EXTERIOR:	White		
				INTERIOR:	Black		
ENGINE:	J08E 7.6L	HP		KEYS: IGNITION: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO • DOOR: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
TRANS:	Automatic	FUEL:	<input type="checkbox"/> GAS <input checked="" type="checkbox"/> DIESEL	ANTIFREEZE TESTED: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
DOES MOTOR RUN?		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		COLLISION DAMAGE? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
PHYSICAL APPEARANCE							
	GD	FR	PR	N/A	COMMENTS	OPTIONS	
BODY	FRONT BUMPER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> PWR STEERING
	HEADLIGHTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		BRAKES
	HOOD	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> AIR
	TURN SIGNALS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> HYD
	GRILLE	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> PWR LOCKS
	D FRONT FENDER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> PWR WINDOWS
	D DOOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> PWR SEATS
	D BOX	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Bulged Out. Rivots Popped Out, Holes	<input type="checkbox"/> PWR MIRRORS
	REAR BUMPER	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/> AIR CONDITIONER
	TAILLIGHTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> AIR RIDE SEAT D/P D
REAR PANEL	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Door On Blocks, Doesn't Move	<input type="checkbox"/> AIR RIDE SUSPENSION	
P FRONT FENDER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> AM FM RADIO	
P FRONT DOOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> CD / CB? CD	
P BOX	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Dent, Hole	<input type="checkbox"/> SLEEPER SIZE? _____	
TOP	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/> TRANSLUCENT ROOF	
TIRES	D FRONT	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	% 0 SIZE: 11R22.5	<input type="checkbox"/> E-TRACK LINING
	D REAR A1 (S/D?)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	% 50 SIZE: 11R22.5	<input type="checkbox"/> BOX DOME LIGHT
	D REAR A2 (S/D?)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	% 10 SIZE: 11R22.5	<input type="checkbox"/> SIDE DOOR
	P FRONT	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	% 5 SIZE: 11R22.5	FUEL TANKS
	P REAR A1 (S/D?)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	% 10 SIZE: 11R22.5	<input type="checkbox"/> SINGLE GAL _____
	P REAR A2 (S/D?)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	% 10 SIZE: 11R22.5	<input type="checkbox"/> DUAL GAL _____
	SPARE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	% SIZE:	<input checked="" type="checkbox"/> MUD FLAPS
GLASS	WINDSHIELD	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Chip And Cracked	WHEELS
	D FRONT DOOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> ALUMINUM
	REAR WINDOW	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> STEEL
	P FRONT DOOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> BUD
INTERIOR	MIRRORS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> SPOKE
	DASH	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> EXHAUST S/D? S_
	DOOR PANELS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		SUSPENSION
	SEAT(S)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Driver Side Is Ripped	<input type="checkbox"/> AIR
	FLOORING	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> SPRING
	HEADLINER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> PAD
MECHANICAL	SLEEPER	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/> TANDEM AXLE
	BOX	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Unable To Open Door, Chipped And Broken Wood, Sections Of Plywood Are Missing, Holes	<input type="checkbox"/> ENGINE BRAKE
		GD	FR	PR	UKN	N/A	COMMENTS:
	ENGINE	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Check Engine Light
	TRANSMISSION	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	CLUTCH	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
	DIFFERENTIALS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	BRAKES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
FRONT END	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
REAR END	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
BATTERY/ELECTR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
REFRIGERATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE							
COMMENTS: Mileage Unverified. Interior and exterior of box has damage.							

RTR Services Inc. • 395 Market St. NE Salem OR 97301 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125