RTR Services Inc. BOX TRUCK									RTR #:        5013892-01          ACCOUNT NUMBER:							
CONDITION REPORT																
YEAR: 2017		MILES 352,325					VIN #:			<b>BOX WIDTH</b> 102"						
		Hino		GVW:		25,95	O BO	X HEIGH	1	BOX LEI	-		-		102"	
		268A	T		WHEELBASE			K				hite		NTERIOR: Gray/Black		ζ.
		J08E 7.6L					GAS 🖾 DIESEL		KEYS: IGNITION: $\boxtimes$ YES $\square$ NO • DOOR ANTIFREEZE TESTED: $\square$ YES $\boxtimes$ NO							
TRANS:  Automatic    DOES MOTOR RUN?				1									NG:			
DOES MOTOR RUN? 🛛 YES 🗌 NO COLLISION DAMAGE? 🗌 YES 🖾 NO PHYSICAL APPEARANCE																
			GD	FR	PR	N/A	COM	IENTS						(	OPTIONS	
вору	FRONT BUMPER HEADLIGHTS HOOD TURN SIGNALS GRILLE D FRONT FENDER			$\boxtimes$									BRAKES			
				$\boxtimes$												
				$\boxtimes$										🖂 HYD		
				$\boxtimes$									$\dashv$	PWR LO	INDOWS	
	D DOOR			$\boxtimes$										PWR S	EATS	
B	D BOX REAR BUMPER		╞	$\boxtimes$		┼┼									IRRORS	
				$\boxtimes$										AIR RID	DE SEAT D/P	
	REAR PANEL			$\boxtimes$			Paint	chipping	g/ Rust					AIR RIE AM FM	DE SUSPENSIO	N
	P FRONT DOOR			$\boxtimes$										CD / CE	3?	
	P BOX □ TOP □		$\boxtimes$											ER SIZE? LUCENT ROOF	-	
TIRES	D FRONT						% 75	SIZE: 11	R22.5				$\dashv$		CK LINING	
	D REAR A1 (S/D?)								: 11R22.5					BOX DO	OME LIGHT	
	D REAR A2 (S/D?)			$\square$			%	SIZE:						SIDE D		
								SIZE: 11	R22.5 : 11R22.5					EL TANK	S GLE GAL	
	P REAR A2 (S/D?)						% 20/	SIZE:							LGAL	_
	SPARE WINDSHIELD		<u> </u>				%	SIZE:						MUD FI	_APS	
s	D FRONT DOOR			$\boxtimes$											MINUM	
GLAS:		AR WINDOW		$\boxtimes$												
0	P FRONT DOOR MIRRORS			$\boxtimes$									-		KE	
	DASH			$\boxtimes$											ST S/D?	_
0R	DOOR PANELS SEAT(S)			$\boxtimes$										SPENSIO	<b>VIN</b>	
NTERI	FLOOR	FLOORING		$\boxtimes$												
Ξ	HEADLINER SLEEPER			$\square$									$\neg$		MAXLE	
	BOX			$\boxtimes$											E BRAKE	
	ENGINE		GD	FR	PR		<u>N/A</u>	COMME	ENTS:					TOOL E	AG AXLE	
۲		TRANSMISSION		$\boxtimes$										RAMP		
MECHANICAL		CLUTCH DIFFERENTIALS		$\square$											A SYSTEM	
	BRAKE	BRAKES		$\boxtimes$												
	FRONT END REAR END			$\boxtimes$												
	BATTERY/ELECTR			$\boxtimes$				Batteri	es replaced	1 3/25						
ти		GERATION						INSPECT			ELING					
то	VALIDA <sup>.</sup>	TE / WE RECO	MMEND											-0, 0010		
		S: Mileage Unv	ermea.													
		EMPLOYEE'S FULI			DDINT	<u>,                                     </u>	_3/2	26/25 DATE				EMPLOYEE'S	SIGNAT	IDE		
			All information	tion cor	itained v	, within this ı	eport is deer		e and accurate	to the best of my l	nowledg	ge as of the date li				

RTR Services Inc. • 395 Market St. NE Salem OR 97301 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125