RTR Services Inc. TRAILER					RTR #: 5021940									6-02				
CONDITION REPORT					T	ACCOUNT NAME:												
		2009			BODY	TYPE:	Норре	er		VIN #: 1TDH422239B120958								
MAKE:		Timpte					•											
MODEL: N		MH202)2		COLOR:		EXTERIOR: 1		White/Sil	White/Silver		INTERI		TERIOR:				
LENGTH:		42'			WIDTH:		8' 5"		HEI	HEIGHT:					GVW : 19,000			
HITCH:		☐ GOOSE NECK		⊠ PI	☑ PINTLE ☐ 5 TH		WHEEL	WHEEL PIN ☐ 1 7/8" BALL ☐ 2" BALL ☐ 2 5/1				2 5/16" BA	BALL					
CAN IT BE TOWED? ⊠ YES			S I	□ №	0	OLLISION DAMAGE?						KEYS	:	☐ YES	⊠ NO			
PHYSICAL APPEARANCE																		
	EDON'T DAN'E		GD	FR	PR	N/A	COMMENTS							OPTIONS				
вору	FRONT PANEL HITCH D SIDE PANEL SIDE DOOR (S) REAR PANEL REAR DOOR (S) P SIDE PANEL						Damaged							☐ AIR RIDE SUSPENSION ☐ SPRING SUSPENSION				
					\boxtimes		Damaged							☐ AIR BRAKES				
																☐ ELECTRICAL BRAKES		
							Dented						☐ HYD BRAKES☐ SLIDER AXLE					
							Dented						WHEELS					
	REAR BUMPER TOP													□ BUD □ SPOKE				
	FLOOR														STEEL	_		
S.	D SIDE PANELS					\boxtimes	Dente	Dented								☐ ALUMINUM ☐ LIFT/TAG AXLE ☑ SPARE TIRE RACK		
INTERIOR	FRONT PANEL P SIDE PANEL					\boxtimes												
K	CARGO RAILS					\boxtimes									☐ HUB METER			
	CEILING					\boxtimes	0/ 40	0175. 445	/E0D00 E						REEFER HRS			
TIRES	D REAR A1 (S/D?) D REAR A2 (S/D?)						% 40 %									☐ TOOL BOX ☑ MUD FLAPS		
	D REAR A3 (S/D?)					\boxtimes	%	% SIZE:							ROLL UP REAR DOOR			
	P REAR A1 (S/D?) P REAR A2 (S/D?)						% 35 SIZE: 445/50R22.5 % SIZE: 445/50R22.5 % SIZE:							│				
	P REAR A3 (S/D?) SPARE															LOADING		
							% SIZE:								☐ TRANSLUCENT ROOF			
ECHANICAL	TAILLIGHTS SIGNAL LIGHTS CLEARANCE LGT SLIDER AXLES REFRIGERATION LANDING GEAR AIR HOSE/GLAD ELECTR PIGTAIL		GD	FR	PR 🖂	UKN	N/A	COMMENTS:							_	☐ INTERIOR LIGHTII ☐ LOADING RAMP		
					\boxtimes			Missing two signal lights								BULL HO		
N												E-TRACK LINING						
CH/																		
ME																		
					□ □ □ ⊠ Missing □ □ □ □ ⊠ Missing wires, no brakes, no airlines, no pigtail													
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / FOR REEFER UNITS: EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE													, BUYER					
						END YO	U INSP	ECT PRIC	K TO PUR	CHAS	E							
COMMENTS: Grain dispenser is locked up.																		
							5/·	16/2025										
		EMPLOYEE'S FUL	L NAME (PLEASE	E PRINT		- J/	DATE					EMP	LOYEE'S SIG	SNATII	RE		
			•		-		oort is deer	ned to be true	and accurate	to the he	est of my	knowledo						