RTR Services Inc.						A	Œ,		RTR #: 50230				077-0	77-01		
FLAT BED/TOW TRUCK								ACCOUNT NUMBER:								
CONDITION REPORT			RT					7	ACCOUNT NAME:							
YEAR:		2009		MIL	MILES U		Unknown		VIN#:	1FVXA7000	A70009DAK1819					
MAKE:		Freightliner		G۷	<b>GVW</b> : 60,00		0 BED WIDT			BED LE	NGTH	GTH		CAPACITY		
MODEL:		Columbia 120		WH	WHEELBASE:		Tri Axle		COLOR: EXTERIOR:		Navy/	// INTERIOR:		Red		
ENGINE:		Detroit DD13		HP	HP UK		KE		EYS: IGNITION: X YES NO • [		• DOOR:	R: ⊠ YES □ NO				
TRANS:		Manual	FU	EL: [	GAS	DIESEL AN		NTIFREEZE TESTED: 🛛 YES 🗌 NO		NO	RATING:					
DOES M		OTOR RUN?		S NO		CA	N IT BE	DRIVEN?	☐ YES	⊠ NO	COLLISION D		/IAGE?	☐ YES	⊠ NO	
						PHY		PHYSICA	AL APPEARANCE							
				FR	PR	N/A	COM	MENTS						OP1	TIONS	
	_	FRONT BUMPER		$\boxtimes$	10									PWR STE	ERING	
	HEAD LIGHTS HOOD			$\boxtimes$									BRA	AKES □ AIR		
		TURN SIGNALS										-				
	GRILL												$\exists  \Box$	PWR LOCKS PWR WINDOWS		
BODY	D FRONT FENDER															
	D DOO		$\boxtimes$										PWR SEA	TS		
	D PANEL													PWR MIRRORS		
	REAR GATE			님	]								$\perp \boxtimes$	AIR COND		
		TAIL LIGHTS											$\exists \exists$	AIR RIDE	SUSPENSION	
				$\boxtimes$									76	AM FM RA		
				$\boxtimes$											/ CB? CB_	
	P PANEL			$\boxtimes$										HITCH TY		
	TOP				$\perp \square$							$\sqcup \Box$	WHEEL LI			
TIRES					][	]	50 %		ZE:				$\dashv \Box$	TANDEM A		
	D REAR A1 (S/D?)			$\boxtimes$			50 % SIZE: 50 % SIZE:					_ =	<ul><li>☐ ENGINE BRAKE</li><li>☐ TOOL BOX</li></ul>			
	P FRONT						50 %		ZE:					EL TANKS	`	
	P REAR A1 (S/D?)			$\boxtimes$			50 % SIZE:						SINGLE GAL			
	P REAR A2 (S/D?)		$\boxtimes$			50 %		ZE:					☐ DUAL (			
	SPARE  WINDSHIELD		=		$\Box$			%	SIZE:					MUD FLAF	28	
S D FROM REAR V P FROM MIRRO		NT DOOR											_ ****	LLL3 ⊠ ALUMII	NUM	
		WINDOW											☐ STEEL			
		NT DOOR									☐ BUD					
		RS					<b>-</b>							☐ SPOKE		
DASH OOR SEAT(3		DANELS					Exposed Wires.						│			
													- 303	SUSPENSION  ⊠ AIR  □ SPRING		
Ä	HEADLINER [ BED [													☐ PAD		
				<u></u>	$\boxtimes$		Bed Is Rusted							LIFT/TAG	AXLE	
AL	ENGIN	=	GD	FR	PR	UKN	N/A	COMME Multiple					48	WINCH J HOOKS/	CHAIN	
	TRANSMISSION					$\boxtimes$		wuitiple	coues				$\exists \exists$	WET KIT	CHAIN	
_ ⊇	CLUTCH												$\exists \exists$	BOOM		
MECHANICAL	DIFFERENTIALS					$\boxtimes$								FLATBED		
	BRAKES					$\boxtimes$								SELF LOA		
	_	FRONT END											$\dashv \Box$		LENGTH	
	BATTE												$\dashv \square$	CAMERA : Tri Axle	SISIEW	
COMMENTS: Milliage Unverified.																
									_							
							3/	10/2025								
	-	EMPLOYEE'S FULI	NAME (P	LEASE	PRINT	)		DATE				EMPLOYEE'S	SIGNATU	RE	<del></del>	

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present