D.T.D. O.		DTD // COOCCO		
RTR Services Inc.		RTR #: 5023266		
GENERAL EQUIPMENT		ACCOUNT		
	ON REPORT		ACCOUNT NAME:	
YEAR:	2019		FOURNITH WAS IN USE AT THE TIME OF DESCRIPTIVE	
MAKE:	Ditch Witch	☐ YES ⊠ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	JT20	☐ OPERATIONAL		
S/N:	DWPJT20BJK000009	□ NON-OPERATIONAL		
POWER:	Diesel	UNTESTABLE		
DESCRIPTION: No Remote, rods are not being grabbed from the rack				
SHOT / COUNT / HOUR: 4,799				
NOTES / COMMENTS: Hours Unverified.				
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE				
	ervices Inc.		RTR #:	
	EQUIPMENT		ACCOUNT	
	ON REPORT		ACCOUNT NAME:	
YEAR:				
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:		OPERATIONAL		
S/N:		□ NON-OPERATIONAL		
POWER:		UNTESTABLE		
DESCRIPTION:				
SHOT / COUNT / HOUR:				
NOTES / COMMENTS:				
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE				
	ervices Inc.		RTR #:	
	EQUIPMENT		ACCOUNT	
	ON REPORT		ACCOUNT NAME:	
YEAR:				
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:		OPERATIONAL		
S/N:		□ NON-OPERATI		
POWER:		UNTESTABLE		
DESCRIPTION:				
SHOT / COUNT / HOUR:				
NOTES / COMMENTS:				
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE				
2/19/2025				
EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE				
All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.				