RTR Services Inc.										RTR #: 502343				35			
FLAT BED/TOW TRUCK										ACCOUNT NUMBER:							
CONDITION REPORT				90			7	ACCOUNT NAME:									
YEAR: 2018			MILES		451480			VIN#:	1FDUF5GY	DUF5GY6JEB43964							
MAKE: Ford		Ford		GV	GVW: 2		26000 BED \		96 IN BED LENGTH 14FT		14FT	TOW CAPACITY		Υ	5000		
MODEL:		F-550		WH	WHEELBASE:		14 ft		COLOR: EXTERIOR: White		White	INTERIOR:		(Gray		
ENGINE: 6.8		6.8L V10			HP			KE	EYS: IGNITION: X YES NO • DOOR:			: 🛛 Y I	⊠ YES □ NO				
TRANS: Autor		Automatic		FUEL:		GAS	_ DIESE	L AN	NTIFREEZE TESTED: ☐ YES ⊠ NO		NO	RATING:					
DOES MOTOR RUN?			⊠ YE	⊠ YES □ NO			AN IT BE	DRIVEN?	☐ YES			ISION DA	MAGE	? 🛭 YE	S	□ NO	
PHYSICAL APPEARANCE																	
			GD	FR	PR	N/A	_	MENTS					OPTIONS				
ВОДУ	FRONT BUMPER HEAD LIGHTS HOOD TURN SIGNALS GRILL							Damage Driver side held in by a strap (zip tie)									
			$\mid \; \mid \; \mid \; \mid$	\square			Dam		и иг бу а ѕtгар (zip tie)				┦╹	☐ AIR ⊠ HYD			
				\boxtimes													
							Dam	age					💆	=		_	
	D FRONT FENDER [D DOOR [\boxtimes										-			
	D PANEL				l 🗖								$\dashv reve{lark}$				
	REAR GATE												□ №	=		TIONER	
	TAIL LIGHTS			\boxtimes									ᅴ┢	_		EAT D/P USPENSION	
	P FRONT FENDER			\boxtimes	Н								$\dashv k$		_		
	P FRONT DOOR			\boxtimes] TAPE/		CB?	
	P PANEL			\boxtimes									-			E	
TIRES	D FRONT							% 225/70DR19.5 SIZE:				\dashv \vdash	-	WHEEL LIFT TANDEM AXLE			
	D REAR A1 (S/D?)		. — :					% 225/70DR19.5 SIZE:						☐ ENGINE BRAKE ☐ TOOL BOX			
	` ' =							% SIZE:									
	P REAR A1 (S/D?)							% 225/70DR19.5 SIZE: % 225/70DR19.5 SIZE:			⊣ 「	FUEL TANKS SINGLE GAL					
	P REAR A2 (S/D?)							%	SIZE:					AL			
	SPARE							%	SIZE:					MUD FI	AP:	S	
တ	WINDSHIELD D FRONT DOOR			\boxtimes									⊣ "	/HEELS ⊠ ALU	MIN	шм	
LAS	_	REAR WINDOW		\boxtimes										☐ STE		···	
เอ	P FRONT DOOR			\boxtimes													
	MIRRORS DASH			\boxtimes									$\dashv_{\scriptscriptstyle{lackbox{\tiny $lackbox{\tiny }}}}}}}}}}}}}}$	☐ SPO EXHAU		S/D2	
꿈	DOOR	i i	\boxtimes										USPENSIC				
RIO	SEAT(S)						Wear	· & tear						☐ AIR			
INTER	FLOORING HEADLINER			\boxtimes									_	⊠ SPR □ PAD			
_	BED			\boxtimes									╛] LIFT/TA	LIFT/TAG AXLE		
ICAL	ENGIN	GD	FR	PR 🖂	UKN	I N/A □	COMME		no oil press	curo ond	l no oil				HAIN		
	TRANSMISSION CLUTCH DIFFERENTIALS BRAKES FRONT END			Ш					a ticking no		ouie allo	i ilo oli,	-	3 HOO!	\J/U		
								Transmi	Transmission is non operational			⊒ ⊑		Т			
AN												-					
MECHANICAL													\dashv $\stackrel{\scriptscriptstyle{\vdash}}{\vdash}$			DER	
								Damage									
									senger side leaf springs are broken d/ It needs to be Jumped.			\dashv F					
CO			verified					Dead/ It	neeus to D	z Juilipea.				1			
COMMENTS: Mileage Unverified																	
							2	18 25									

EMPLOYEE'S FULL NAME (PLEASE PRINT)

DATE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present