

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT		RTR #: 5023522-02	
		ACCOUNT	
		ACCOUNT NAME:	
YEAR:	2023		
MAKE:	Allmand	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:	GR-Series Liquid	<input checked="" type="checkbox"/> OPERATIONAL	
S/N:	37-004077	<input type="checkbox"/> NON-OPERATIONAL	
POWER:	Kubota Diesel	<input type="checkbox"/> UNTESTABLE	
DESCRIPTION:	Trailer mounted vertical light tower.		
SHOT / COUNT / HOUR: 3,175			
NOTES / COMMENTS: Hours Unverified			
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE			

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT		RTR #: 5023522-03	
		ACCOUNT	
		ACCOUNT NAME:	
YEAR:	2023		
MAKE:	Allmand	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:	GR-Series Liquid	<input type="checkbox"/> OPERATIONAL	
S/N:	37-004080	<input checked="" type="checkbox"/> NON-OPERATIONAL	
POWER:	Kubota Diesel	<input type="checkbox"/> UNTESTABLE	
DESCRIPTION:	Trailer mounted vertical light tower		
SHOT / COUNT / HOUR: 3,780			
NOTES / COMMENTS: Hours Unverified. Starter sylinoid is bad and it won't start. VIN: 5AEA1NA14PH012863			
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE			

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT		RTR #: 5023522-04	
		ACCOUNT	
		ACCOUNT NAME:	
YEAR:	2023		
MAKE:	Allmand	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:	GR-Series Liquid	<input checked="" type="checkbox"/> OPERATIONAL	
S/N:	37-004087	<input type="checkbox"/> NON-OPERATIONAL	
POWER:	Kubota Diesel	<input type="checkbox"/> UNTESTABLE	
DESCRIPTION:	Trailer mounted vertical light tower		
SHOT / COUNT / HOUR: 776			
NOTES / COMMENTS: Hours Unverified. VIN: 5AEA1NA11PH012870			
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE			

4/24/25

EMPLOYEE'S FULL NAME (PLEASE PRINT)

DATE

EMPLOYEE'S SIGNATURE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.