

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT		RTR #: 5023522-05	
		ACCOUNT	
		ACCOUNT NAME:	
YEAR:	2023		
MAKE:	Allmand	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:	GR-Series Liquid	<input checked="" type="checkbox"/> OPERATIONAL	
S/N:	37-004090	<input type="checkbox"/> NON-OPERATIONAL	
POWER:	Kubota Diesel	<input type="checkbox"/> UNTESTABLE	
DESCRIPTION:	Trailer mounted vertical light tower		
SHOT / COUNT / HOUR: 2,960 Hours Unverified			
NOTES / COMMENTS:			
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE			

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT		RTR #: 5023522-06	
		ACCOUNT	
		ACCOUNT NAME:	
YEAR:	2023		
MAKE:	Allmand	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:	GR-Series Liquid	<input type="checkbox"/> OPERATIONAL	
S/N:	37-004163	<input checked="" type="checkbox"/> NON-OPERATIONAL	
POWER:	Kubota Diesel	<input type="checkbox"/> UNTESTABLE	
DESCRIPTION:	Trailer mounted vertical light tower		
SHOT / COUNT / HOUR: 3,092			
NOTES / COMMENTS: Hours Unverified. Engine starts. Generator does not work. VIN : 5AEA1NA1XPh013161			
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE			

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT		RTR #:	
		ACCOUNT	
		ACCOUNT NAME:	
YEAR:			
MAKE:		<input type="checkbox"/> YES <input type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:		<input type="checkbox"/> OPERATIONAL	
S/N:		<input type="checkbox"/> NON-OPERATIONAL	
POWER:		<input type="checkbox"/> UNTESTABLE	
DESCRIPTION:			
SHOT / COUNT / HOUR:			
NOTES / COMMENTS:			
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE			

EMPLOYEE'S FULL NAME (PLEASE PRINT)

DATE

EMPLOYEE'S SIGNATURE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125