	RTR	Services In		RTR #: 5023642-01															
TRAILER					ACCOUNT NUMBER:														
CONDITION REPORT					7	7 04	9 9 9		ACCOUNT NAME:										
YEAR:		2022			BODY TYPE:		Dump			VIN #: 4P53D2631N30597			9780	80					
	MAKE:	-																	
MODEL:		Dump Trailer			COLOR:		EXTERIOR:			Black			IN	TERIOR:	Black				
LENGTH:		26'			WIDTH:		WHEEL PIN			HEIGHT: 24"					GVW : 21,000			0	
HITCH: GOOSE NE		1					_		8" BALL										
CAN IT BE TOWED? ☐ YES ☐ NO COLLISION DAMAGE? ☐ YES ☐ NO KEYS: ☐ YES ☐ NO													⊠ NO						
								PHYSICAL APPEARANCE											
	FRONT PANEL		GD	FR 🖂	PR	N/A	COMMENTS							OPTIONS AIR RIDE SUSPENSION				N	
BODY	HITCH D SIDE PANEL			\boxtimes			Goos	eneck slightly twisted								SPRING SUSPENSION			
							_									AIR BRAKES ELECTRICAL BRAKES			
															_	J			
	REAR DOOR (S)			\boxtimes										SLIDER AXLE					
	P SIDE PANEL														WH	EELS			
	REAR BUMPER															_ □ BUD □ SPOKE			
INTERIOR	FLOOR														1	⊠ ST	_		
	D SIDE PANELS														_ ALUMINUM				
	FRONT PANEL P SIDE PANEL CARGO RAILS			\boxtimes										☐ LIFT/TAG AXLE ☐ SPARE TIRE RACK					
															☐ HUB METER			_	
	CEILING					\boxtimes										☐ REEFER HRS			
	D REAR A1 (S/D?) D REAR A2 (S/D?)				\boxtimes			SIZE: ST2								TOOL MUD I			
တ္ပ	D REAR A3 (S/D?)														_		EAR DOOR		
TIRES	P REAR A1 (S/D?) P REAR A2 (S/D?) P REAR A3 (S/D?) SPARE			\boxtimes				% 40 SIZE: ST235/80R16							☐ BATTERY				
-				\boxtimes			% 40 % 40	% 40 SIZE: ST235/80R16 % 40 SIZE: ST235/80R16						☐ LIFTGATE☐ LOADING R			ΡΔΜΡ		
							% SIZE:] 🗇				
ECHANICAL	TAILLIGHTS		GD	FR	PR	UKN	N/A COMMENTS:												
	SIGNAL LIGHTS CLEARANCE LGT SLIDER AXLES REFRIGERATION LANDING GEAR			\boxtimes			\parallel									BULL	_		
															E-TRACK LINING				
																Tri Ax	le		
								Inerope	rable										
Σ	AIR HO					\square													
TUI		<u>R PIGTAIL</u> ΓΑ ΜΕCHANIO		SDEC.		IT IS A \	/ [] / SIIAI	INSDECT	ON ONI	V / FOR	DEEEE	D HMI	TQ. E	MISSION	S NO.	TVEDIE	EIED	BLIVED	
		SLE TO VALID										-14 0141	13. L		3 NO	I VLIXII	ILD,	DOTER	
co	MMENTS	8: Braces und	ler trail	er are	broke	n loose.	Hydrau	lic Ram is	Inside	the traile	r bed. I	Batteri	es mi	issing.					
							4/3	3/25											
EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE																			
			All inform	ation co	ntained v	rithin this re	port is deer	ned to be true	and accur	rate to the be	est of my k	nowledg	e as of	the date lister	l above).			