

RTR Services Inc. UTILITY TRUCK CONDITION REPORT				RTR #:	5024391-01			
				ACCOUNT NUMBER:				
				ACCOUNT NAME:				
YEAR:	2012	VIN #:	1FVACXDT1CDBX0588			MILES:	91,656	
MAKE:	Freightliner	BODY TYPE:	Utility/Bucket Truck					
MODEL:	M2	GVW:	33,000	COLOR:	EXTERIOR: White	INTERIOR:	Gray	
ENGINE:	Cummins ISB	KEYS: IGNITION:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	DOOR:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
TRANS:	Automatic	FUEL:	<input type="checkbox"/> GAS <input checked="" type="checkbox"/> DIESEL <input type="checkbox"/> HYBRID	ANTIFREEZE TESTED:		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	RATING	
DOES MOTOR RUN?		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	COLLISION DAMAGE?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
PHYSICAL APPEARANCE								
BODY	FRONT BUMPER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	N/A	COMMENTS		<input checked="" type="checkbox"/> PWR STEERING <input checked="" type="checkbox"/> PWR BRAKES <input type="checkbox"/> PWR LOCKS <input type="checkbox"/> PWR WINDOWS <input type="checkbox"/> PWR SEATS <input type="checkbox"/> LEATHER SEATS <input type="checkbox"/> PWR MIRRORS <input type="checkbox"/> CRUISE CONTROL <input type="checkbox"/> TILT WHEEL <input type="checkbox"/> TINTED GLASS <input checked="" type="checkbox"/> AIR CONDITIONER <input type="checkbox"/> CUSTOM WHEELS <input checked="" type="checkbox"/> AM/FM RADIO <input type="checkbox"/> CD PLAYER <input type="checkbox"/> NAVIGATION <input type="checkbox"/> BACKUP CAMERA <input type="checkbox"/> 4 X 4 <input type="checkbox"/> TOW PACKAGE <input type="checkbox"/> CUSTOM WHEELS <input type="checkbox"/> SUNROOF <input checked="" type="checkbox"/> UTILITY BODY <input checked="" type="checkbox"/> BUCKET <input type="checkbox"/> OUTRIGGERS <input type="checkbox"/> TOOL BOX
	HEADLIGHTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
	HOOD	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
	TURN SIGNALS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
	GRILLE	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
	D FRONT FENDER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
	D DOOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
	D REAR FENDER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
	CARGO BED	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
	REAR BUMPER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
TAILLIGHTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>					
TAILGATE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>					
TIRES	P FRONT FENDER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
	P DOOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
	P REAR FENDER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
	TOP	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
	D FRONT	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>		60 % SIZE: 22.5		
D REAR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>		60 % SIZE: 22.5			
P FRONT	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>		60 % SIZE: 22.5			
P REAR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>		60 % SIZE: 22.5			
SPARE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		% SIZE:			
GLASS	WINDSHIELD	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
	D FRONT DOOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
	D REAR PANEL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
	P FRONT DOOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
	P REAR PANEL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
	REAR WINDOW	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
INTERIOR	DASH	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
	DOOR PANELS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
	SEAT(S)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>				
	CARPET	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
	HEADLINER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
	GD	FR	PR	UKN	N/A	COMMENTS:		
MECHANICAL	ENGINE	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	It takes a little bit to build air pressure (probably the compressor is going out) other than that it is fully operable.		
	TRANSMISSION	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
	CLUTCH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
	BRAKES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
	FRONT END	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
	REAR END	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
	BATTERY/ELECTR	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Batteries Replaced 6/25		
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE								
COMMENTS: Mileage Unverified. It takes some time to build air pressure.								

5/29/25

EMPLOYEE'S FULL NAME (PLEASE PRINT)

DATE

EMPLOYEE'S SIGNATURE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125