RTR Services Inc. FLATBED/CAR HAULER CONDITION REPORT							VINNI		RTR #: ACCOUNT ACCOUNT NAME:			5033067-01			
YEAR: 2008		JKI	BODY TYPE:		TYPE:	Flatbed		VIN #: 4WWBGB6B38N612991			12991				
MAKE:		Wilson				R CAPA			VIII III.	-111112020.	500110	12001			
MODEL:		Flatbed	latbed		C	OLOR:	EXTERIOR: Alumir		num/ Brown						
LENGTH:		48'			WIDTH:		8' 5"		HEIGHT: 4' 5"				<b>GVW</b> : 55,000		
HITCH:		☐ GOOSE N	E NECK		PINTLE S 5TH		WHEEL PIN		BALL 2" BALL 2 5/16" B			5/16" BAL	ALL		
CAN IT BE TOWED?		⊠ YE	YES NO		C	COLLISION DAMA	AGE?	☐ YES	⊠ NO	KEY	YS: [	☐ YES	⊠ NO		
							PHYSICAL	. APPEAF	RANCE					,	
			GD	FR	PR	N/A	COMMENTS							TIONS	
TIRES BODY	FRONT PANEL HITCH D SIDE PANEL D SIDE TIE DOWNS REAR PANEL P SIDE TIE DOWNS P SIDE PANEL REAR BUMPER TOP RAMP(S) SIDE DOOR REAR DOOR D REAR A1 (S/D?) D REAR A2 (S/D?) P REAR A1 (S/D?) P REAR A2 (S/D?)						Wavy near the driver front  % 80 SIZE: 295/75R22.5  % 80 SIZE: 295/75R22.5								
MECHANICAL	TAILLIC SIGNAL CLEAR SLIDER LANDII AIR HO	R A3 (S/D?)	300 <b>6</b> 00000		PR		% 80 SIZE: 295 % SIZE: 295 N/A COMM	5/75R22.5					WEDGE WINCH SPARE TII REAR DOO TANDEM A SIDE DOO LIFT/TAG ENCLOSE	OR AXLE R AXLE	
							- MOUAL INOPE				ID VOI	[	= = = = = = = = = = = = = = = = = = = =		
		NOT A MECHA					A VISUAL INSPE	CTION O	NLY / WE I	RECOMMEN	ND YOU	U INSPEC	T PRIOR TO	PURCHASE	
		EMPLOYEE'S FULI	L NAME (P	LEASI	PRINT)		4/8/2025 DATE				EMPLOY	YEE'S SIGNA	ATURE		