RTR Services Inc. FLATBED/CAR HAULER CONDITION REPORT				4			INNAME		ACCOUNT ACCOUNT NAME:			67-02		
YEAR: 2007				BODY TYPE:		Flatbed		VIN #: 4WWBGB6B27N611782			2			
MAKE:		Wilson			CA	R CAPA	CITY							
MODEL:		Flatbed			COLOR:		EXTERIOR: Alumin		num/ Brown					
LENGTH:		48'			WIDTH:				HEIGHT: 4' 5"			GVW:	GVW : 55,000	
HITCH: GOOSE NECK			ECK	☐ PI	NTLE	⊠ 5 TH	WHEEL PIN			LL 🗌 2" BALL 🔲 2 5/16" B			ALL	
CAN IT BE TOWED? ⊠ YES				s	□ NO	С	COLLISION DAMAGE?		☐ YES	⊠ NO	KEYS:	☐ YES	⊠ NO	
PHYSICAL APPEARANCE														
			GD	FR	PR	N/A	COMMENTS						OPTIONS	
ВОДУ	FRONT PANEL HITCH D SIDE PANEL D SIDE TIE DOWNS REAR PANEL P SIDE TIE DOWNS P SIDE PANEL REAR BUMPER TOP RAMP(S) SIDE DOOR REAR DOOR		0000000000				☐ SPRING S ☑ AIR BRAK						RICAL BRAKES RAKES RAXLE O OKE EL IMINUM	
TIRES	D REALD REALD REALD REALD PREALD PREA					% 80 SIZE: 295/75R22.5 % SIZE: 295/75R22.5					MUD F LOADII BATTE DOVE TILT BI WEDGI	☐ MUD FLAPS		
MECHANICAL	TAILLIGHTS SIGNAL LIGHTS CLEARANCE LGT SLIDER AXLES LANDING GEAR AIR HOSE/GLAD ELECTRIC PIGTAI			FR	PR								REAR DOOR TANDEM AXLE SIDE DOOR IFT/TAG AXLE ENCLOSED	
	THIS IS	NOT A MECHA	NICAL	INSP	ECTIO	N/IT IS	A VISUAL INSPE	CTION O	NLY / WE F	RECOMME	ND YOU INS		TO PURCHASE	
		S: Passenger												
	4/8/2025 EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE													