RTR Services Inc.										RTR #: 5041243									
HEAVY TRUCK CONDITION REPORT										ACCOUNT NUMBER:ACCOUNT NAME:									
YEAR: 2015		MI	LES	643,237	7		VIN #:												
MAKE: Freightliner			GV	GVW: 33		LICENSE:		-	-	ST:		TAGS:	MON	тн		YR:			
MODEL: Cascadia 113			WHEELBASE:		180		COLOR:					INTERIOR: Gray/Tan							
ENGINE: Detroit DD13			HP		BODY TYP		_	Day Cab											
TRANS: Automatic						DIESEL ANTIFREEZE TESTED: VES NO						RATI	NG:						
	DOES M	OTOR RUN?	🛛 YE	S	□ NO	C			GE? 🛛 Y		NO 🛛								
	GD		FR	PR	N/A	COMMEN								OPTIONS					
вору	HEAD LIGHTS [HOOD [TURN SIGNALS] GRILLE [
				\boxtimes									BRAKES AIR HYD PWR LOCKS						
				\boxtimes															
				\boxtimes										\square			CKS IDOWS		
	D DOOR			\boxtimes										\square	PWR			, ,	
	D SLEEPER												$\square \boxtimes$			RORS	ED		
	TAILLIGHTS		\boxtimes													SEAT			
	REAR PANELP FRONT FENDER						-							\exists			SUSPI ^H WHE		
	-			\boxtimes													5 TH WH		
																	-		
TIRES	D FRONT			\boxtimes			50 % 295	/75R	22.5 SIZE:					\square			D / CB? R SIZE?		
	D REAR A1 (S/D?)			\boxtimes				40 % 295/75R22.5 SIZE:											
				\square			90 % 295/75R22.5 SIZE: 30 % 295/75R22.5 SIZE:								☐ GLAD HANDS FUEL TANKS				
	P REAR A1 (S/D?)			\boxtimes		15 % 295/75R22.5 SIZE:													
	P REAR A2 (S/D?)			\square			95 % SIZE: % SIZE:								☐ DUAL GAL ☐ MUD FLAPS				
	WINDSHIELD														WHEELS				
GLASS	D FRONT DOOR REAR WINDOW P FRONT DOOR MIRRORS DASH			\boxtimes									⊠ ALUMINUM □ STEEL						
				\boxtimes									□ BUD □ SPOKE □ EXHAUST S/D?						
							Front driver side mirror is broken										\neg		
R	DOOR PANELS SEAT(S)			\boxtimes											SPENS				
ERIOR				\boxtimes															
INTI	CARPET HEADLINER			\boxtimes										_	□ SI □ P/		G		
	SLEEPER					\square									TAN	DEM	AXLE		
MECHANICAL	ENGINE		GD	FR	PR				IENTS:					ᅱ님	ENG TOO		3RAKE X		
	TRANSMISSION			\boxtimes											LIFT/	TAG	AXLE		
	CLUTCH DIFFERENTIALS			\boxtimes											WET	KIT			
	BRAKES			\bowtie															
	FRONT END			\boxtimes										\exists					
	BATTERY/ELECTR		\square																
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE																			
COMMENTS: Mileage Unverified.																			
5/5/25																			
	I	EMPLOYEE'S FULL					port is deemed to	DATE		to the best	of my kn		EMPLOYEE'S						

RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125