RTR Services Inc.						mili.	T		RTR # : 5043127–01								
DUMP TRUCK										ACCOUNT NUMBER:							
CONDITION REPORT									ACCOUNT NAME:								
YEAR:		2016			_ES	511,892			VIN:	#: 1	1NKDXPEX5GJ499151						
MAKE:		Kenworth		GVW:		78,350	BEI	HEIGHT	5'	' BED LENGTH 16' BE		BED V	SED WIDTH 8'				
MODEL:		T880		WH	WHEELBAS				COLOR: EXTERIOR:		_	Red			y/Black		
ENGINE:		Paccar		HP					EYS: IGNITION: 🛛 YES 🗌 NO • DOOR								
TRANS:		Automatic				GAS 🛛					ESTED: YES	⊠ NO	RATIN	RATING:			
DOES MOTOR RUN? 🖾 YES 🗌 NO COLLISION DAMAGE? 🖾 YES 🗌 NO PHYSICAL APPEARANCE																	
			0.0	ED		NIA			L APPE	AKAN	NGE			OPTIONS			
	FRONT BUMPER HEADLIGHTS HOOD		GD	<u>FR</u> ⊠	PR	N/A	COM	MENTS						PWR S	OPTION TEERIN	_	
				\boxtimes										AKES			
													_				
	TURN SIGNALS GRILLE			\boxtimes									\dashv_{\bowtie}	☐ HYD PWR L			
ı	D FRONT FENDER			X										PWR W		IS .	
ВОВУ	D DOOR			\boxtimes										PWR SI			
	D DUMP BED ERAR GATE																
	REAR GATE			\boxtimes									$\dashv \boxtimes$	AIR CONDITIONER AIR RIDE SEAT D/P			
	REAR PANEL			\boxtimes									$\dashv \exists$	☐ AIR RIDE SUSPENSION ☐ AM FM RADIO			
	P FRONT FENDER			\boxtimes]												
	P FRONT DOOR P DUMP BED			\boxtimes									\dashv \boxminus	CD / CE		_	
	TOP						Passe	nger side	damao	red			$\dashv \exists$	TARP SYSTEM		 1	
TIRES	D FROI			\boxtimes		Passenger side damaged % 30 SIZE: 385/65R22.5						$\dashv \exists$	☐ TANDEM AXLE				
	D REAR A1 (S/D?)							SIZE : 11]						☐ ENGINE BRAKE			
	D REAR A2 (S/D?)				\boxtimes		% 30						TOOL BOX				
	P FRONT						% 30 SIZE : 385/65R22.5						FUEL TANKS SINGLE GAL				
	P REAR A1 (S/D?)						% 30 SIZE : 11R24.5										
	P REAR A2 (S/D?)							% 30 SIZE : 11R24.5					DUAL GAL				
	SPARE WINDSHIELD			\blacksquare			% SIZE:			<u> </u>							
GLASS	D FRONT DOOR						Severe damage collision Collision damage					WHEELS					
	REAR WINDOW						Complete damage						☐ STEEL				
ច P FRO		NT DOOR											□ BUD □ SPOKE				
	MIRRORS						Driver side broken off										
œ	DASH DOOR PANELS													EXHAU SPENSIO		?	
INTERIOR	SEAT(S)					$\mid \; \mid \; \mid \; \mid \; \mid$							_ 303	DENSIO	'IN		
	•	FLOORING		\boxtimes										☐ SPR			
Z	HEADLINER												4,,	☐ PAD		_	
	DUMP BED		GD	FR	PR	UKN	N/A	COMME	NTS:				$\dashv \dashv$	LIFT/ TA			
MECHANICAL	ENGINE TRANSMISSION CLUTCH DIFFERENTIALS			\boxtimes									$\neg \vdash$	BED CA			
													$\dashv \exists$				
	BRAKES												$\dashv \exists$				
	FRONT END REAR END BATTERY/ELECTR			\boxtimes			🗇										
			뮈								_	·					
THI			CAL INS	⊠ PEC1	ION /	IT IS A V	│	NSPECTI	ON ONI	LY / D	EF & DPF FUNCT	IONS NOT V	L <u>L</u> ∕ERIFIF	D. BUYF	R RES	PONSIBLE	
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE																	
COI	MMENTS	S: Mileage Unv	erified.														
							4/3	30/25									

DATE

EMPLOYEE'S FULL NAME (PLEASE PRINT)

EMPLOYEE'S SIGNATURE