


RTR Services Inc. TRAILER CONDITION REPORT				RTR #: 5043524-06				
		ACCOUNT NUMBER:						
		ACCOUNT NAME:						
YEAR:	2018	BODY TYPE:	Reefer	VIN #:	1UYVS2530J2262218			
MAKE:	Utility							
MODEL:	VS2RA	COLOR:	EXTERIOR: White	INTERIOR:	White			
LENGTH:	53'	WIDTH:	8'6"	HEIGHT:	13'6" GVW: 65,000			
HITCH:	<input type="checkbox"/> GOOSE NECK <input type="checkbox"/> PINTLE <input checked="" type="checkbox"/> 5 TH WHEEL PIN <input type="checkbox"/> 1 7/8" BALL <input type="checkbox"/> 2" BALL <input type="checkbox"/> 2 5/16" BALL							
CAN IT BE TOWED?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	COLLISION DAMAGE?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	KEYS:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
PHYSICAL APPEARANCE								
		GD	FR	PR	N/A	COMMENTS	OPTIONS	
BODY	FRONT PANEL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> AIR RIDE SUSPENSION	
	HITCH	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> SPRING SUSPENSION	
	D SIDE PANEL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> AIR BRAKES	
	SIDE DOOR (S)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> ELECTRICAL BRAKES	
	REAR PANEL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> HYD BRAKES	
	REAR DOOR (S)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> SLIDER AXLE	
	P SIDE PANEL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		WHEELS	
	REAR BUMPER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> BUD	
INTERIOR	TOP	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> SPOKE	
	FLOOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> STEEL	
	D SIDE PANELS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> ALUMINUM	
	FRONT PANEL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> LIFT/TAG AXLE	
	P SIDE PANEL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> SPARE TIRE RACK	
	CARGO RAILS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/> HUB METER	
TIRES	CEILING	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> REEFER HRS <u>27245</u>	
	D REAR A1 (S/D?)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	% 10 SIZE: 295/75/22.5	<input type="checkbox"/> TOOL BOX	
	D REAR A2 (S/D?)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	% 10 SIZE: 295/75/22.5 Wheel rim broken	<input checked="" type="checkbox"/> MUD FLAPS	
	D REAR A3 (S/D?)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	% 10 SIZE: 295/75/22.5	<input type="checkbox"/> ROLL UP REAR DOOR	
	P REAR A1 (S/D?)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	% 10 SIZE: 295/75/22.5	<input type="checkbox"/> BATTERY	
	P REAR A2 (S/D?)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	% 10 SIZE: 295/75/22.5	<input type="checkbox"/> LIFTGATE	
	P REAR A3 (S/D?)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	% 10 SIZE: 295/75/22.5	<input type="checkbox"/> LOADING RAMP	
	SPARE	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	% SIZE:	<input type="checkbox"/> TRANSLUCENT ROOF	
MECHANICAL		GD	FR	PR	UKN	N/A	COMMENTS:	<input type="checkbox"/> INTERIOR LIGHTING
	TAILLIGHTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> LOADING RAMP
	SIGNAL LIGHTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> BULL HOOKS
	CLEARANCE LGT	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> E-TRACK LINING
	SLIDER AXLES	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Excess rust built up	
	REFRIGERATION	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	LANDING GEAR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	AIR HOSE/GLAD	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	ELECTR PIGTAIL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Batteries replaced 5/25	
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / FOR REEFER UNITS: EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE								
COMMENTS: Dents and scrapes throughout Tire Inflation System Missing PSI Lines								

5/28/25

EMPLOYEE'S FULL NAME (PLEASE PRINT)

DATE

EMPLOYEE'S SIGNATURE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.

RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125