

RTR Services Inc. DUMP TRUCK CONDITION REPORT				RTR #: 5043649	
		ACCOUNT NUMBER:			
		ACCOUNT NAME:			
YEAR:	2008	MILES	285,622	VIN#:	1M1AX09Y38M002466
MAKE:	Mack	GVW:		BED HEIGHT	60"
MODEL:	GU713	WHEELBASE:		COLOR: EXTERIOR:	Red
ENGINE:	Mack MP8 12.7L	HP	450	KEYS: IGNITION:	☒ YES ☐ NO • DOOR: ☒ YES ☐ NO
TRANS:	Manual	FUEL:	☐ GAS ☐ DIESEL	ANTIFREEZE TESTED:	☐ YES ☒ NO
DOES MOTOR RUN?	☒ YES ☐ NO	CAN IT BE DRIVEN?	☒ YES ☐ NO	COLLISION DAMAGE?	☐ YES ☒ NO
PHYSICAL APPEARANCE					
		GD	FR	PR	N/A
	COMMENTS				
BODY	FRONT BUMPER	☐	☒	☐	☐
	HEAD LIGHTS	☐	☒	☐	☐
	HOOD	☐	☒	☐	☐
	TURN SIGNALS	☐	☒	☐	☐
	GRILL	☐	☒	☐	☐
	D FRONT FENDER	☐	☒	☐	☐
	D DOOR	☐	☒	☐	☐
	D DUMP BED	☐	☒	☐	☐
	REAR GATE	☐	☒	☐	☐
	TAIL LIGHTS	☐	☒	☐	☐
TIRES	REAR PANEL	☐	☒	☐	☐
	P FRONT FENDER	☐	☒	☐	☐
	P FRONT DOOR	☐	☒	☐	☐
	P DUMP BED	☐	☒	☐	☐
	TOP	☐	☒	☐	☐
	D FRONT	☐	☒	☐	☐
	D REAR A1 (S/D?)	☐	☒	☐	☐
	D REAR A2 (S/D?)	☐	☒	☐	☐
	P FRONT	☐	☒	☐	☐
	P REAR A1 (S/D?)	☐	☒	☐	☐
GLASS	P REAR A2 (S/D?)	☐	☒	☐	☐
	SPARE	☐	☐	☐	☒
	WINDSHIELD	☐	☒	☐	☐
	D FRONT DOOR	☐	☒	☐	☐
	REAR WINDOW	☐	☒	☐	☐
INTERIOR	P FRONT DOOR	☐	☒	☐	☐
	MIRRORS	☐	☒	☐	☐
	DASH	☐	☒	☐	☐
	DOOR PANELS	☐	☒	☐	☐
	SEAT(S)	☐	☒	☐	☐
MECHANICAL	FLOORING	☐	☒	☐	☐
	HEADLINER	☐	☒	☐	☐
	DUMP BED	☐	☒	☐	☐
		GD	FR	PR	UKN
		N/A	COMMENTS:		
	ENGINE	☐	☒	☐	☐
	TRANSMISSION	☐	☒	☐	☐
	CLUTCH	☐	☒	☐	☐
DIFFERENTIALS	☐	☒	☐	☐	
BRAKES	☐	☒	☐	☐	
FRONT END	☐	☒	☐	☐	
REAR END	☐	☒	☐	☐	
BATTERY/ELECTR	☐	☒	☐	☐	

COMMENTS: Mileage unverified.

9/14/2022

EMPLOYEE'S FULL NAME (PLEASE PRINT)

DATE

EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107